


# Technical Guidance



V, 5bâ • d^ à` q |KÁ  
 Ô\} d a p Á ^ & @ & } } a Ò Š V Ò Ô P Á ] È Á È È  
 ~ | B o a i ^ & } a F È È Á | È È È Á , ã } ã a  
 c | È Á | Á Ì Á Ğ | È È È a a | Á Ì Á Ğ | Á È  
 , , , È | c & @ & { È | Á Á | c & @ ^ | c & @ & { È |

# Reference

R1 ~ R7

Steel and Non-Ferrous Metal Symbols Chart.....	R2
Hardness Scale Comparison Chart.....	R4
Standard of Tapers.....	R5
Finished Surface Roughness.....	R6
Tolerance Chart for Round Matching Parts.....	R7

## ■ Steel and Non-Ferrous Metal Symbols Chart

### ● Carbon Steels

JIS	AISI	DIN
S10C	1010	C10
S15C	1015	C15
S20C	1020	C22
S25C	1025	C25
S30C	1030	C30
S35C	1035	C35
S40C	1040	C40
S45C	1045	C45
S50C	1049	C50
S55C	1055	C55

### ● Ni-Cr-Mo Steels

SNCM220	8620	—
SNCM240	8640	—
SNCM415	—	—
SNCM420	4320	—
SNCM439	4340	—
SNCM447	—	—

### ● Cr Steels

SCr415	—	—
SCr420	—	—
SCr430	5130	34Cr4
SCr435	5135	37Cr4
SCr440	5140	41Cr4
SCr445	5147	—

### ● Cr-Mo Steels

SCM415	—	—
SCM420	—	—
SCM430	4130	—
SCM435	4135	34CrMo4
SCM440	4140	42CrMo4
SCM445	4145	—

### ● Mn Steels and Mn-Cr Steels for Structural Use

SMn420	1522	—
SMn433	1536	—
SMn438	1541	—
SMn443	1541	—
SMnC420	—	—
SMnC443	—	—

### ● Cr-Mo Steels

SK1	W1-13	—
SK2	W1-11 1/2	—
SK3	W1-10	C105W1
SK4	W1-9	—
SK5	W1-8	C80W1
SK6	W1-7	C80W1
SK7	—	C70W2

### ● High Speed Steels

JIS	AISI	DIN
SKH2	T1	—
SKH3	T4	—
SKH10	T15	—
SKH51	M2	S6-5-2
SKH52	M3-1	—
SKH53	M3-2	S6-5-3
SKH54	M4	—
SKH56	M36	—

### ● Alloy Tool Steels

SKS11	F2	—
SKS51	L6	—
SKS43	W2-9 1/2	—
SKS44	W2-8 1/2	—
SKD1	D3	X210Cr12
SKD11	D2	—

### ● Grey Cast Iron

FC100	20	GG-10
FC150	25	GG-15
FC200	30	GG-20
FC250	35	GG-25
FC300	40	GG-30
FC350	50	GG-35

### ● Nodular Cast Iron

FCD400	—	GGG-40
FCD450	60/40/8	GGG-40.3
FCD500	65/45/12	GGG-50
FCD600	80/55/06	GGG-60
FCD700	100/70/03	GGG-70

### ● Ferritic Stainless Steels

SUS405	AISI 405	DINX6CrAl13
SUS429	AISI 429	—
SUS430	AISI 430	DINX6Cr17
SUS430F	AISI 430F	DINX12CrMoS17
SUS434	AISI 434	—

### ● Martensitic Stainless Steels

SUS403	AISI 403	—
SUS410	AISI 410	DINX10Cr13
SUS416	AISI 416	—
SUS420JI	AISI 420	DINX20Cr13
SUS420F	AISI 420F	—
SUS431	AISI 431	DINX20CrNi172
SUS440A	AISI 440A	—
SUS440B	AISI 440B	—
SUS440C	AISI 440C	—

### ● Austenitic Stainless Steels

JIS	AISI	DIN
SUS201	AISI 201	—
SUS202	AISI 202	—
SUS301	AISI 301	—
SUS302	AISI 302	—
SUS302B	AISI 302B	—
SUS303	AISI 303	DINX10CrNiS189
SUS303Se	AISI 303Se	—
SUS304	AISI 304	DINX5CrNi1810
SUS304L	AISI 304L	DINX2CrNi1911
SUS304NI	AISI 304N	—
SUS305	AISI 305	DINX5CrNi1812
SUS308	AISI 308	—
SUS309S	AISI 309S	—
SUS310S	AISI 310S	—
SUS316	AISI 316	DINX5CrNiMo17122
SUS316L	AISI 316L	DINX2CrNiMo17132
SUS316N	AISI 316N	—
SUS317	AISI 317	DINX2CrNiMo18164
SUS317L	AISI 317L	—
SUS321	AISI 321	—
SUS347	AISI 347	DINX6CrNiNb1810
SUS384	AISI 384	—

### ● Heat Resisting Steels

SUH31	—	—
SUH35	—	—
SUH36	—	—
SUH37	—	—
SUH38	—	—
SUH309	AISI 309	—
SUH310	AISI 310	DINCrNi2520
SUH330	AISI 330	—

### ● Ferritic Heat Resisting Steels

SUH21	—	DINCrAl1205
SUH409	AISI 409	DINX6CrTi12
SUH446	AISI 446	—

### ● Martensitic Heat Resisting Steels

SUH1	—	—
SUH3	—	—
SUH4	—	—
SUH11	—	—
SUH600	—	—

■ Steel and Non-Ferrous Metal Symbols Chart

● Classifications and Symbols of Steels

Class	Material	Symbol	Symbol's Rationale	
Structural Steels	Rolled Steels for welded structures	SM	"M" for "Marine" - Usually used in welded marine structures	
	Re-rolled Steels	SRB	"R" for "Re-rolled" and "B" for "Bar"	
	Rolled Steels for general structures	SS	"S" for "Steel" and for "Structure"	
	Light gauge sections for general structures	SSC	"C" for "Cold"	
Steel Sheets	Hot rolled mild steel sheets / plates in coil form	SPH	"P" for "Plate" and "H" for "Hot"	
	Carbon steel tubes for piping	SGP	"GP" for "Gas Pipe"	
Steel Tubes	Carbon steel tubes for boiler and heat exchangers	STB	"T" for "Tube" and "B" for "Boiler"	
	Seamless steel tubes for high pressure gas cylinders	STH	"H" for "High Pressure"	
	Carbon steel tubes for general structures	STK	"K" for "Kozo" - Japanese word meaning "structure"	
	Carbon steel tubes for machine structural uses	STKM	"M" for "Machine"	
	Alloy steel tubes for structures	STKS	"S" for "Special"	
	Alloy steel tubes for pipings	STPA	"P" for "Piping" and "A" for "Alloy"	
	Carbon steel tubes for pressure pipings	STPG	"G" for "General"	
	Carbon steel tubes for high temperature pipings	STPT	"T" for "Temperatures"	
	Carbon steel tubes for high pressure pipings	SPS	"S" after "SP" is abbreviation for "Special"	
	Stainless steel tubes for pipings	SUS-TP	"T" for "Tube" and "P" for "Piping"	
	Steel for Machine Structures	Carbon steels for machine structural uses	SxxC	"C" for "Carbon"
		Aluminium Chromium Molybdenum steels	SACM	"A" for "Al", "C" for "Cr" and "M" for "Mo"
		Chromium Molybdenum steels	SCM	"C" for "Cr" and "M" for "Mo"
Chromium steels		SCr	"Cr" for "Chromium"	
Nickel Chromium steels		SNC	"N" for "Nickel" and "C" for "Chromium"	
Nickel Chromium Molybdenum steels		SNCM	"M" for "Molybdenum"	
Manganese steels for structural use Manganese Chromium steels		SMn SMnC	"Mn" for "Manganese" "C" for "Chromium"	
Special Steels	Carbon tool steels	SK	"K" for "Kogu" - Japanese word meaning "tool"	
	Hollow drill steels	SKC	"C" for "Chisel"	
	Alloy tool steel	SKS SKD SKT	"S" for "Special" "D" for "Die" "T" for "Tanzo" - Japanese word for "forging"	
	High speed tool steels	SKH	"H" for "High speed"	
	Free cutting sulfuric steels	SUM	"M" for "Machinability"	
	High Carbon Chromium bearing steels	SUJ	"J" for "Jikuuke" - Japanese word meaning "bearing"	
	Spring steels	SUP	"P" for "Spring"	
	Stainless steels	SUS	"S" after "SU" is abbreviation for "Stainless"	
	Heat-resistant Steels	Heat-resistant steels	SUH	"U" for "Special Usage" and "H" for "Heat"
		Heat-resistant steel bars	SUHB	"B" for "Bar"
Heat-resistant steel sheets		SUHP	"P" for "Plate"	
Forged Steels	Carbon steel forgings for general use	SF	"F" for "Forging"	
	Carbon steel booms and billets for forgings	SFB	"B" for "Billet"	
	Chromium Molybdenum steel forgings	SFCM	"C" for "Chromium" and "M" for "Molybdenum"	
	Nickel Chromium Molybdenum steel forgings	SFNCM	"N" for "Nickel"	
Cast Irons	Grey cast irons	FC	"F" for "Ferrous" and "C" for "Casting"	
	Spherical graphite / Ductile cast irons	FCD	"D" for "Ductile"	
	Blackheart malleable cast irons	FCMB	"M" for "Malleable" and "B" for "Black"	
	Whiteheart malleable cast irons	FCMW	"W" for "White"	
	Pearlite malleable cast irons	FCMP	"P" for "Pearlite"	
Cast Steels	Carbon cast steels	SC	"C" for "Casting"	
	Stainless cast steels	SCS	"S" for "Stainless"	
	Heat-resistant cast steels	SCH	"H" for "Heat"	
	High Manganese cast steels	SCMnH	"Mn" for "Manganese" and "H" for "High"	

● Non-Ferrous Metals

Class	Material	Symbol	
Copper and Copper Alloys	Copper and Copper alloys - Sheets, plates and strips	CxxxxP	
		CxxxxPP	
		CxxxxR	
	Copper and Copper alloys - Welded pipes and tubes	CxxxxBD	
		CxxxxBDS	
		CxxxxBE CxxxxBF	
Aluminium and Aluminium Alloys	Aluminium and Al alloys - Sheets, plates and strips	AxxxxP AxxxxPC	
		AxxxxBE AxxxxBD AxxxxW	
	Aluminium and Al alloys - Rods, bars and wires	AxxxxS	
	Aluminium and Al alloys - Extruded shapes	AxxxxFD AxxxxFH	
	Aluminium and Al alloy forgings		
	Magnesium Alloys	Magnesium alloy sheets and plates	MP
	Nickel Alloys	Nickel-Copper alloy sheets and plates	NCuP
Nickel-Copper alloy rods and bars		NCuB	
Wrought Titanium	Titanium rods and bars	TB	
Castings	Brass castings	YBxCx	
	High strength Brass castings	HBxCx	
	Bronze castings	BCx	
	Phosphorus Bronze castings	PCBx	
	Aluminium Bronze castings	AIBCx	
	Aluminium alloy castings	AC	
	Magnesium alloy castings	MC	
	Zinc alloy die castings	ZDCx	
	Aluminium alloy die castings	ADC	
	Magnesium alloy die castings	MDC	
	White metals	WJ	
	Aluminium alloy castings for bearings	AJ	
Copper-Lead alloy castings for bearings	KJ		

## ■ Hardness Scale Comparison Chart

Brinell Hardness (HB) 3,000kgf	Rockwell Hardness				Vickers Hardness 50kgf	Shore Hardness	Traverse Rupture Strength (kg/mm <sup>2</sup> )
	"A" Scale 60kgf (Brale)	"B" Scale 100kgf (1/10" Ball)	"C" Scale 150kgf (Brale)	"D" Scale 100kgf (Brale)			
—	85.6	—	68.0	76.9	940	97	—
—	85.3	—	67.5	76.5	920	96	—
—	85.0	—	67.0	76.1	900	95	—
767	84.7	—	66.4	75.7	880	93	—
757	84.4	—	65.9	75.3	860	92	—
745	84.1	—	65.3	74.8	840	91	—
733	83.8	—	64.7	74.3	820	90	—
722	83.4	—	64.0	73.8	800	88	—
712	—	—	—	—	—	—	—
710	83.0	—	63.3	73.3	780	87	—
698	82.6	—	62.5	72.6	760	86	—
684	82.2	—	61.8	72.1	740	—	—
682	82.2	—	61.7	72.0	737	84	—
670	81.8	—	61.0	71.5	720	83	—
656	81.3	—	60.1	70.8	700	—	—
653	81.2	—	60.0	70.7	697	81	—
647	81.1	—	59.7	70.5	690	—	—
638	80.8	—	59.2	70.1	680	80	—
630	80.6	—	58.8	69.8	670	—	—
627	80.5	—	58.7	69.7	667	79	—
601	79.8	—	57.3	68.7	640	77	—
578	79.1	—	56.0	67.7	615	75	—
555	78.4	—	54.7	66.7	591	73	210
534	77.8	—	53.5	65.8	569	71	202
514	76.9	—	52.1	64.7	547	70	193
495	76.3	—	51.0	63.8	528	68	186
477	75.6	—	49.6	62.7	508	66	177
461	74.9	—	48.5	61.7	491	65	170
444	74.2	—	47.1	60.8	472	63	162
429	73.4	—	45.7	59.7	455	61	154
415	72.8	—	44.5	58.8	440	59	149
401	72.0	—	43.1	57.8	425	58	142
388	71.4	—	41.8	56.8	410	56	136
375	70.6	—	40.4	55.7	396	54	129
363	70.0	—	39.1	54.6	383	52	124
352	69.3	(110.0)	37.9	53.8	372	51	120
341	68.7	(109.0)	36.6	52.8	360	50	115
331	68.1	(108.5)	35.5	51.9	350	48	112


Brinell Hardness (HB) 3,000kgf	Rockwell Hardness				Vickers Hardness 50kgf	Shore Hardness	Traverse Rupture Strength (kg/mm <sup>2</sup> )
	"A" Scale 60kgf (Brale)	"B" Scale 100kgf (1/10" Ball)	"C" Scale 150kgf (Brale)	"D" Scale 100kgf (Brale)			
321	67.5	(108.0)	34.3	50.1	339	47	108
311	66.9	(107.5)	33.1	50.0	328	46	105
302	66.3	(107.0)	32.1	49.3	319	45	103
293	65.7	(106.0)	30.9	48.3	309	43	99
285	65.3	(105.5)	29.9	47.6	301	—	97
277	64.6	(104.5)	28.8	46.7	292	41	94
269	64.1	(104.0)	27.6	45.9	284	40	91
262	63.6	(103.0)	26.6	45.0	276	39	89
255	63.0	(102.0)	25.4	44.2	269	38	86
248	62.5	(101.0)	24.2	43.2	261	37	84
241	61.8	100.0	22.8	42.0	253	36	82
235	61.4	99.0	21.7	41.4	247	35	80
229	60.8	98.2	20.5	40.5	241	34	78
223	—	97.3	(18.8)	—	234	—	—
217	—	96.4	(17.5)	—	228	33	74
212	—	95.5	(16.0)	—	222	—	72
207	—	94.6	(15.2)	—	218	32	70
201	—	93.8	(13.8)	—	212	31	69
197	—	92.8	(12.7)	—	207	30	67
192	—	91.9	(11.5)	—	202	29	65
187	—	90.7	(10.0)	—	196	—	63
183	—	90.0	(9.0)	—	192	28	63
179	—	89.0	(8.0)	—	188	27	61
174	—	87.8	(6.4)	—	182	—	60
170	—	86.8	(5.4)	—	178	26	58
167	—	86.0	(4.4)	—	175	—	57
163	—	85.0	(3.3)	—	171	25	56
156	—	82.9	(0.9)	—	163	—	53
149	—	80.8	—	—	156	23	51
143	—	78.7	—	—	150	22	50
137	—	76.4	—	—	143	21	47
131	—	74.0	—	—	137	—	46
126	—	72.0	—	—	132	20	44
121	—	69.8	—	—	127	19	42
116	—	67.6	—	—	122	18	41
111	—	65.7	—	—	117	15	39

1) Figures within the ( ) are not commonly used

2) Rockwell A, C and D scales utilises a diamond brale

Standard of Tapers

Morse Taper



(Units in mm)

Morse Taper Number	Taper*	Taper Angle (α°)	Taper						Tang						Shape	
			D	d	D <sub>1</sub> <sup>+</sup> (Estimated)	d <sub>1</sub> <sup>+</sup> (Estimated)	l <sub>1</sub> (Max)	l <sub>2</sub> (Max)	d <sub>2</sub> (Max)	b	C (Max)	e (Max)	R	r		
0	1/19.212	0.05205	1°29'27"	9.045	3	9.2	6.1	56.5	59.5	6.0	3.9	6.5	10.5	4	1	Fig 1
1	1/20.047	0.04988	1°25'43"	12.065	3.5	12.2	9.0	62.0	65.5	8.7	5.2	8.5	13.5	5	1.2	
2	1/20.020	0.04995	1°25'50"	17.780	5	18.0	14.0	75.0	80.0	13.5	6.3	10	16	6	1.6	
3	1/19.922	0.05020	1°26'16"	23.825	5	24.1	19.1	94.0	99.0	18.5	7.9	13	20	7	2	
4	1/19.245	0.05194	1°29'15"	31.267	6.5	31.6	25.2	117.5	124.0	24.5	11.9	16	24	8	2.5	
5	1/19.002	0.05263	1°30'26"	44.399	6.5	44.7	36.5	149.5	156.0	35.7	15.9	19	29	10	3	
6	1/19.180	0.05214	1°29'36"	63.348	8	63.8	52.4	210.0	218.0	51.0	19	27	40	13	4	
7	1/19.231	0.05200	1°29'22"	83.058	10	83.6	68.2	286.0	296.0	66.8	28.6	35	54	19	5	


Morse Taper Number	Taper*	Taper Angle (α°)	Taper						Thread						Shape
			D	d	D <sub>1</sub> <sup>+</sup> (Estimated)	d <sub>1</sub> <sup>+</sup> (Estimated)	l <sub>1</sub> (Max)	l <sub>2</sub> (Max)	d <sub>2</sub> (Max)	d <sub>3</sub>	K (Max)	t (Max)	r		
0	1/19.212	0.05205	1°29'27"	9.045	3	9.2	6.4	50	53	6	—	—	4	0.2	Fig 2
1	1/20.047	0.04988	1°25'43"	12.065	3.5	12.2	9.4	53.5	57	9	M 6	16	5	0.2	
2	1/20.020	0.04995	1°25'50"	17.780	5	18.0	14.6	64	69	14	M10	24	5	0.2	
3	1/19.922	0.05020	1°26'16"	23.825	5	24.1	19.8	81	86	19	M12	28	7	0.6	
4	1/19.254	0.05194	1°29'15"	31.267	6.5	31.6	25.9	102.5	109	25	M16	32	9	1	
5	1/19.002	0.05263	1°30'26"	44.399	6.5	44.7	37.6	129.5	136	35.7	M20	40	9	2.5	
6	1/19.180	0.05214	1°29'36"	63.348	8	63.8	53.9	182	190	51	M24	50	12	4	
7	1/19.231	0.05200	1°29'22"	80.058	10	86.6	70.0	250	260	65	M33	80	18.5	5	

\* The fractional values are the taper standards.

\* Diameters (D<sub>1</sub>) and (d<sub>1</sub>) are calculated from the values of (D) and other values of the taper. (Values are rounded up to one decimal place)

Bottle Grip Taper

American Standard Taper (National Taper)



(Units in mm)

Taper No.	D <sub>1</sub>	D <sub>2</sub>	t <sub>1</sub>	t <sub>2</sub>	t <sub>3</sub>	t <sub>4</sub>	t <sub>5</sub>	d <sub>1</sub> (Standard)	d <sub>2</sub>	d <sub>3</sub>	d <sub>4</sub>	L	l <sub>1</sub>	l <sub>2</sub>	l <sub>3</sub>	l <sub>4</sub>	g	b <sub>1</sub>	t <sub>7</sub>	Reference		Shape
																				d <sub>5</sub>	l <sub>1</sub>	
BT40	63	53	25	10	16.6	2	2	44.45	19	17	14	65.4	30	8	21	M16	16.1	22.6	25.3	70	Fig 1	
BT45	85	73	30	12	21.2	3	3	57.15	23	21	17.5	82.8	38	9	26	M20	19.3	29.1	33.1	70		
BT50	100	85	35	15	23.2	3	3	69.85	27	25	21	101.8	45	11	31	M24	25.7	35.4	40.1	90		
BT60	155	135	45	20	28.2	3	3	107.95	33	31	26.5	161.8	56	12	34	M30	25.7	60.1	60.7	110		




American Standard Taper (National Taper)

(Units in mm)

Taper No.	Nominal Diameter	D	d <sub>1</sub>	L	l <sub>1</sub>	l <sub>2</sub>	l <sub>3</sub>	g	a	t	b	Shape
30	1 1/4"	31.750	17.40	70	20	24	50	1/2"	1.6	15.9	16	Fig 2
40	1 3/4"	44.450	25.32	95	25	30	60	5/8"	1.6	15.9	22.5	
50	2 3/4"	69.850	39.60	130	25	45	90	1"	3.2	25.4	35	
60	4 1/4"	107.950	60.20	210	45	56	110	1 1/4"	3.2	25.4	60	

## ■ Finished Surface Roughness

### ● Types of Surface Roughness Measurements

Types	Symbol	Method of Determination	Descriptive Figure
Maximum Height	Ry	This is the value (expressed in $\mu\text{m}$ ) measured from the deepest valley to the highest peak of the reference line, $\ell$ , extracted from the profile.  (Disregard unusually high peaks and deep valleys as they are considered as flaws.)	
Ten-point Mean Roughness	Rz	From the profile, extract a portion to be the reference line, $\ell$ .  Select the 5 highest peak and 5 deepest valleys. Measure the distance between the two lines and express it in $\mu\text{m}$ .	
Calculated Roughness	Ra	This method is to obtain a center line between the peaks and valleys within the reference line, $\ell$ . Fold along the center line to superimpose the valleys against the peaks. (Shaded portions with dashed outline on the right figure). Take the total shaded area and divided it by $\ell$ in $\mu\text{m}$ .	

Designated values of the above types of surface roughness, standard reference length values and the triangular symbol classifications are shown on the table on the right.

Designated values for Ry	Designated values for Rz	Designated values for Ra	Standard reference length values, $\ell$ (mm)	Triangular Symbols
(0.05S) 0.1S 0.2S 0.4S	(0.05Z) 0.1Z 0.2Z 0.4Z	(0.013a) 0.025a 0.05a 0.10a	—	
0.8S	0.8Z	0.20a	0.25	
1.6S 3.2S 6.3S	1.6Z 3.2Z 6.3Z	0.40a 0.80a 1.6a	0.8	
12.5S (18S) 25S	12.5Z (18Z) 25Z	3.2a 6.3a	2.5	
(35S) 50S (70S) 100S	(35Z) 50Z (70Z) 100Z	12.5a 25a	—	
(140S) 200S (280S) 400S (560S)	(140Z) 200Z (280Z) 400Z (560Z)	(50a) (100a)	—	—

Remarks: The designated values in the brackets do not apply unless otherwise stated.

■ Tolerance Chart for Round Matching Parts

● Tolerance for Shank Sizes

Diameter, D(mm)		Tolerance Class (µm)																
>D	≤D	b9	c9	d8	d9	e7	e8	e9	f6	f7	f8	g5	g6	h5	h6	h7	h8	h9
-	3	-140 -165	-60 -85	-20 -34	-20 -45	-14 -24	-14 -28	-14 -39	-6 -12	-6 -16	-6 -20	-2 -6	-2 -8	0 -4	0 -6	0 -10	0 -14	0 -25
3	6	-140 -170	-70 -100	-30 -48	-30 -60	-20 -32	-20 -38	-20 -50	-10 -18	-10 -22	-10 -28	-4 -9	-4 -12	0 -5	0 -8	0 -12	0 -18	0 -30
6	10	-150 -186	-80 -116	-40 -62	-40 -76	-25 -40	-25 -47	-25 -61	-13 -22	-13 -28	-13 -35	-5 -11	-5 -14	0 -6	0 -9	0 -15	0 -22	0 -36
10	14	-150 -193	-95 -138	-50 -77	-50 -93	-32 -50	-32 -59	-32 -75	-16 -27	-16 -34	-16 -43	-6 -14	-6 -17	0 -8	0 -11	0 -18	0 -27	0 -43
14	18																	
18	24	-160 -212	-110 -162	-65 -98	-65 -117	-40 -61	-40 -73	-40 -92	-20 -33	-20 -41	-20 -53	-7 -16	-7 -20	0 -9	0 -13	0 -21	0 -33	0 -52
24	30																	
30	40	-170 -232	-120 -182	-80 -119	-80 -142	-50 -75	-50 -89	-50 -112	-25 -41	-25 -50	-25 -64	-9 -20	-9 -25	0 -11	0 -16	0 -25	0 -39	0 -62
40	50																	
50	65	-190 -264	-140 -214	-110 -146	-100 -174	-60 -90	-60 -106	-60 -134	-30 -49	-30 -60	-30 -76	-10 -23	-10 -29	0 -13	0 -19	0 -30	0 -46	0 -74
65	80																	
80	100	-220 -307	-170 -257	-120 -174	-120 -207	-72 -107	-72 -126	-72 -159	-36 -58	-36 -71	-36 -90	-12 -27	-12 -34	0 -15	0 -22	0 -35	0 -54	0 -87
100	120																	
120	140	-260 -360	-200 -300															
140	160	-280 -380	-210 -310	-145 -208	-145 -245	-85 -125	-85 -148	-85 -185	-43 -68	-43 -83	-43 -106	-14 -32	-14 -39	0 -18	0 -25	0 -40	0 -63	0 -100
160	180																	
180	200	-310 -410	-230 -330															
200	225	-340 -455	-240 -355	-170 -242	-170 -285	-100 -146	-100 -172	-100 -215	-50 -79	-50 -96	-50 -122	-15 -35	-15 -44	0 -20	0 -29	0 -46	0 -72	0 -115
225	250																	

● Tolerance for Hole Sizes

Diameter, D(mm)		Tolerance Class (µm)																		
>D	≤D	B10	C9	C10	D8	D9	D10	E7	E8	E9	F6	F7	F8	G6	G7	H6	H7	H8	H9	H10
-	3	+180 +140	+85 +60	+100 +60	+34 +20	+45 +20	+60 +20	+24 +14	+28 +14	+39 +14	+12 +6	+16 +6	+20 +6	+8 +2	+12 +2	+6 0	+10 0	+14 0	+25 0	+40 0
3	6	+188 +140	+100 +70	+118 +70	+48 +30	+60 +30	+78 +30	+32 +20	+38 +20	+50 +20	+18 +10	+22 +10	+28 +10	+12 +4	+16 +4	+8 0	+12 0	+18 0	+30 0	+48 0
6	10	+208 +150	+116 +80	+138 +80	+62 +40	+76 +40	+98 +40	+40 +25	+47 +25	+61 +25	+22 +13	+28 +13	+35 +13	+14 +5	+20 +5	+9 0	+15 0	+22 0	+36 0	+58 0
10	14	+220 +150	+138 +95	+165 +95	+77 +50	+93 +50	+120 +50	+50 +32	+59 +32	+75 +32	+27 +16	+34 +16	+43 +16	+17 +6	+24 +6	+11 0	+18 0	+27 0	+43 0	+70 0
14	18																			
18	24	+244 +160	+162 +110	+194 +110	+98 +65	+117 +65	+149 +65	+61 +40	+73 +40	+92 +40	+33 +20	+41 +20	+53 +20	+20 +7	+28 +7	+13 0	+21 0	+33 0	+52 0	+84 0
24	30																			
30	40	+270 +170	+182 +120	+220 +120	+119 +80	+142 +80	+180 +80	+75 +50	+89 +50	+112 +50	+41 +25	+50 +25	+64 +25	+25 +9	+34 +9	+16 0	+25 0	+39 0	+62 0	+100 0
40	50																			
50	65	+310 +190	+214 +140	+260 +140	+146 +146	+174 +100	+220 +146	+90 +60	+106 +60	+134 +60	+49 +30	+60 +30	+76 +30	+29 +10	+40 +10	+19 0	+30 0	+46 0	+74 0	+120 0
65	80																			
80	100	+360 +220	+257 +170	+310 +170	+174 +120	+207 +120	+260 +120	+107 +72	+126 +72	+159 +72	+58 +36	+71 +36	+90 +36	+34 +12	+47 +12	+22 0	+35 0	+54 0	+87 0	+140 0
100	120																			
120	140	+420 +260	+300 +200	+360 +200																
140	160	+440 +280	+310 +210	+370 +210	+208 +145	+245 +145	+205 +145	+125 +85	+148 +85	+185 +85	+68 +43	+83 +43	+106 +43	+39 +14	+54 +14	+25 0	+40 0	+63 0	+100 0	+160 0
160	180																			
180	200	+470 +310	+330 +230	+390 +230																
200	225	+525 +340	+355 +240	+425 +240																
225	250	+565 +380	+375 +260	+445 +260	+242 +170	+285 +170	+355 +170	+146 +100	+172 +100	+215 +100	+79 +50	+96 +50	+122 +50	+44 +15	+61 +15	+29 0	+46 0	+72 0	+115 0	+185 0

# Turning Guidance

T1 ~ T8

Selecting Cutting Conditions & Cutting Resistance	····T2
Influences of Cutting Edge Geometries	····T3
General Guide Lines for Turning Tools	····T4
Tool Life	····T5
Tool Failures and Their Counter-Measures	····T6
Analysis of Chip Control on Turning	····T7
Factors on Chip Control & Their Influences	····T8

# Turning Guidance

## ■ Selecting Cutting Conditions & Cutting Resistance

< Selection Of Cutting Conditions >

### ● Cutting Conditions & Their Influence

Item	Influencing Matters
Speed	Work Efficiency, Tool Life, Cutting Power Consumption & Surface Roughness
Feed	Work Efficiency, Chip Control, Tool Life, Cutting Power Consumption & Surface Roughness
Depth of Cut	Working Efficiency, Chip Control, Cutting Power Consumption & Dimensional Accuracy

### ● Selecting Cutting Parameters

#### Calculation of Cutting Speed, Table Feed & Cutting Time

Calculating Rotating speed given the Cutting speed:

$$N = \frac{1000 \times V}{\pi \times D}$$

N : Spindle Speed (rpm)  
V : Cutting Speed (m/min)  
D : Work Diameter (mm)  
 $\pi$  : 3.14

If extracting the Cutting Speed from the Rotating Speed:

$$V = \frac{\pi \times D \times N}{1000}$$

The symbols are as described in the above.

Calculating the actual Table Feed (F)


$$F = f \times N$$

Where F is in mm/min

Finally, Calculating the actual Cutting Time (T) in mins.

$$T = \frac{L}{F}$$

Where L is the total cutting length



N : Work Rotating speed (rpm)  
V : Cutting speed (m/min)  
f : Feedrate (mm/rev)  
d : Depth of cut (mm)  
D : Workpiece diameter (mm)

#### Tool Materials and Cutting Speed Ratio

HSS	Carbide	Coated	Cermet	Ceramic
1	3~6	5~15	5~10	10~25

#### Speed Ratio Related to Surface and Machining Conditions of The Work

Turned Surface	Casting & Forging Faces	Continuous Machining	Interuptted Machining
1	0.70	1	0.70

< Cutting Resistance >


### ● Three Component Forces Of Cutting Resistance

### ● Factors Affecting Cutting Resistance

### ● Determination Of Cutting Resistance

### ● Determination Of Power Requirement

#### Three Component Forces:



P1: Principal or Tangential Component Force  
P2: Feed Component Force  
P3: Back Component Force

#### Determination of the Cutting Resistance

$P_1 = P_s \times q$   
P1: Cutting Resistance (kg)  
Ps: Specific Cutting Resistance (kg/mm<sup>2</sup>)  
q: Area of the chip (mm<sup>2</sup>)

#### Determination of Power Requirement

$W = \frac{V \cdot f \cdot d \cdot P_s}{6.12 \times 10^3 \cdot \eta}$   
W : Power Requirement (kW)  
V : Speed (m/min)  
f : Feedrate (mm/rev)  
d : Depth of Cut (mm)  
 $\eta$  : Mechanical Efficiency  
H : Required Horsepower (HP)

#### Approximate Ps value

Normal Steel : 250~300 kg/mm<sup>2</sup>  
Cast Iron : 150kg/mm<sup>2</sup>


#### Factors Influencing Cutting Resistance

Factor	Decrease <- Cutting Resistance -> Increase
1. Workpiece	Low <- Tensile Strength -> High
2. Cutting Area	Small <- Cutting Area -> Large
3. Cutting speed	High <- Cutting Speed -> Low
4. Rake Angle	Large <- Rake Angle -> Small (Positive) (Negative)
5. Approach Angle	Small <- Approach angle -> Large


#### Relation Between Tensile Strength & Cutting Resistance

Tensile Strength (kg/mm <sup>2</sup> )	30~40	40~50	50~60	60~70	70~80	90~100
Cutting Resistance Ratio	1	1.10	1.18	1.29	1.45	1.70


#### Cutting Area & Cutting Resistance



#### Cutting Speed & Cutting Resistance



#### Rake Angle & Cutting Resistance




## ■ Influences of Cutting Edge Geometries

### ● Edge Forms & Their Influences


Kind Of Edge Forms	Strength Of Cutting Edge	Cutting Edge Temperature	Cutting Resistance	Cutting Ability	Tool Life	Surface Finished	Chatter	Chip Flow Direction
1. Back Rake	●		●					●
2. Top or Side Rake	●	●	●	●	●			●
3. Clearance Angle	●			●	●	●	●	
4. Trail Angle	●					●	●	
5. Approach Angle	●		●		●		●	●
6. Nose Radius	●		●		●	●	●	●

### ● Relation Between Rake Angle & Cutting Resistance




### ● Influence Of The Approach Angle :

- \*Relation To The Undeformed Chip Thickness.
- \*Chip Thickness & Specific Cutting Resistance.
- \*Approach Angle & 3 Component Forces.



### ● Influence Of the Nose Radius :

- \*Nose Radius & 3 Component Forces
- \*Nose Radius & Strength



# Turning Guidance

## General Guide Lines for Turning Tools

### Surface Roughness

**Theoretical (Geometric) Surface Roughness**

$$R_{max} = \frac{f^2}{8r}$$

$R_{max}$  : Surface Roughness (mm)  
 $f$  : Feed (mm/rev)  
 $r$  : Nose Radius (mm)

**Steps To Improve Finished Surfaces:**

1. Enlarge the nose radius.
2. Optimise the cutting speed and feed.  
(To set conditions so that the built-up edge may not occur.)
3. Optimise the insert grade

**Variation of Surface Roughness According To The Nose Radius & Feed**

Nose Radius \ Feed	0.4	0.8	1.2
0.15			
0.26			
0.46			

**Actual Surface Roughness:**

In Case of Steels,  
Theoretical Roughness x 1.5~3

In Case of Cast irons,  
Theoretical Roughness x 3~5

### Growth Of The Built-Up Edge & Its Remedies

Built-up edge is a state that while cutting, a portion of the workpiece piles up and adheres to the cutting edge due to work hardening. As an excessively harder degenerated substance than the base metal, the deposited material then acts as the cutting edge.

**Influence of Built-up Edge**

1. Deterioration of Surface Roughness And Accuracy.
2. Increase Edge Chipping

**Steps to Prevent Built-up Edge**

1. Raise the cutting temperature by increasing the speed and feed.
2. Apply cutting fluids that have a satisfactory EP performance.
3. Use coated or cermet tools.
4. Enlarge the rake angle.

**Cycle of Built-up Edge**

### Different Edge Treatments & Their Effects

Different Edge Treatments		Influence of the Width of Negative Land	Influence of the Honing Amount
 Figure 1	Honing		
 Figure 2	Negative Land (Chamfer Honing)		
 Figure 3	Combined Honing		
 Figure 4	Sharp Edge (w/o Edge Treatment)		


$r$  : Honing Amount  
 $\theta$  : Angle Of Negative Land  
 $l$  : Width Of Negative Land

### Factors That Cause Chattering & Some Of Its Remedies


	Poor Workpiece Rigidity	Poor Tool Rigidity	Poor Machine Rigidity	Poor Cutting Conditions	Poor Edge Design
Remedies	<ul style="list-style-type: none"> <li>- Improve clamping.</li> <li>- Use fixed steady.</li> <li>- Improve rigidity of the tail center.</li> </ul>	<ul style="list-style-type: none"> <li>- Use a thicker shank.</li> <li>- Reduce the overhang.</li> <li>- Use a carbide shank holder.</li> <li>- Check that toolholder is held properly.</li> </ul>	<ul style="list-style-type: none"> <li>- Reduce backlash in the main spindle Bearing</li> <li>- Eliminate backlash in machine slides</li> </ul>	<ul style="list-style-type: none"> <li>- Select correct cutting conditions.</li> <li>- Change speed to avoid the sympathetic vibration point.</li> </ul>	<ul style="list-style-type: none"> <li>- Reduce clearance angle.</li> <li>- Reduce approach angle.</li> <li>- Increase the end cutting edge angle.</li> <li>- Reduce the nose radius.</li> <li>- Make the rake angle larger.</li> <li>- Hone the cutting edge slightly.</li> </ul>

## ■ Tool Life

### ● Wear Process Curve



### ● Life Curve (V-T Lines)



### ● Tool Life Equation

Tool Life Equation (Taylor's Equation)

$$VT^n = C$$

V : Cutting speed  
 T : Tool Life  
 n & C : Constants  
 Determined by the Work Material, Tool Material, Tool Design, etc.


### ● Alternative Tool Life Criteria

<ol style="list-style-type: none"> <li>When surface finish deteriorates unacceptably.</li> <li>When a fixed amount of tool wear is reached, (see the right hand table)</li> <li>When work piece dimension is not tolerable.</li> <li>When power consumption reaches a limit.</li> <li>Sparking or chip discolouration and disfiguration.</li> <li>Cutting Time or Number of components produced.</li> </ol>	Width of flank wear for general life determination for cemented carbides.										
	<table border="1"> <thead> <tr> <th>Width of Wear (mm)</th> <th>Applications</th> </tr> </thead> <tbody> <tr> <td>0.2</td> <td>Finish Cutting of Nonferrous Alloys, Fine and Light Cut, etc.</td> </tr> <tr> <td>0.4</td> <td>Cutting of Special Steels and The Like.</td> </tr> <tr> <td>0.7</td> <td>Normal Cutting of Cast Irons, Steels, etc.</td> </tr> <tr> <td>1- 1.25</td> <td>Rough Cutting of Common Cast Irons.</td> </tr> </tbody> </table>	Width of Wear (mm)	Applications	0.2	Finish Cutting of Nonferrous Alloys, Fine and Light Cut, etc.	0.4	Cutting of Special Steels and The Like.	0.7	Normal Cutting of Cast Irons, Steels, etc.	1- 1.25	Rough Cutting of Common Cast Irons.
	Width of Wear (mm)	Applications									
	0.2	Finish Cutting of Nonferrous Alloys, Fine and Light Cut, etc.									
	0.4	Cutting of Special Steels and The Like.									
0.7	Normal Cutting of Cast Irons, Steels, etc.										
1- 1.25	Rough Cutting of Common Cast Irons.										






# Turning Guidance

## ■ Tool Failures and Their Counter-Measures

### ● Characteristic Of Tool Failure

	No.	Failure	Cause	
	1~5	Flank Wear	Physical	Due to the scratching effect of hard grains contained within the work material.
6	Chipping	Fine breakages caused by high pressure cutting, chatter and vibration, etc.		
7	Partial Fracture	Due to mechanical impact when an excessive force is applied to the cutting edge.		
8	Crater Wear	Chemical	Due to a combination of galling and welding between the chips and the top rake.	
9	Plastic Deformation		The cutting edge is deformed due to its softening at high temperature.	
10	Thermal Crack		Thermal fatigue from the heating and cooling cycle during interrupted cutting.	
11	Built-up Edge		The deposition and adhesion of the hardened work material on the cutting edge.	

### ● Failure & Countermeasures

	Failure	Basic Counter-measures		Application Example		
					Steel	Cast Iron
Edge Failure	Excessive Flank Wear 	Tool Material Cutting Conditions	- Use a more wear-resistant grade Carbide --> { Coated Carbide / Cermet } - Decrease Speed	Recommended Insert Grade: Finishing: T110A (Cermet) Rough: AC2000 (Alumina Coated)	Cast Iron BN250 (CBN) AC500G (Alumina Coated) NS260C (Ceramic)	
	Excessive Crater Wear 	Tool Material Tool design Cutting Conditions	- Use a crater-resistant grade. Carbide --> Coated (K--> M--> P) Cermet - Enlarge the rake angle - Select the correct chip breaker - Decrease speed, reduce the depth of cut and feedrate.	Recommended Insert Grade: Finishing: T110A (Cermet) Rough Machining: AC2000 (Alumina Coated)	Cast Iron BN250 (CBN) AC500G (Alumina Coated)	● Use MU Type Chip Breaker
	Cutting Edge Chipping 	Tool Material Tool design Cutting Conditions	- Use tougher grades. If carbides: P10 -> P20 -> P30 K01 -> K10 -> K20 - If built-up edge occurs, change to a less susceptible grade eg. cermet. - Reinforce the cutting edge eg. Honing. - Reduce the rake angle. - Increase speed (If there is edge build-up).	Recommended Insert Grade: Finishing: T1200A (Cermet) Rough Machining: AC3000 (Alumina Coated)	Cast Iron AC500G (Coated) AC500G (Alumina Coated) NS260 (Ceramic)	● Edge Treatment : All of our inserts have been honed in advance.
	Partial Fracture Of Cutting Edges 	Tool Material Tool design Cutting Conditions	- Use tougher grades. For carbides: P10 -> P20 -> P30 K01 -> K10 -> K20 - Use the holder with a larger approach angle. - Use a holder with a larger shank size. - Reduce the depth of cut and feedrate.	Recommended Insert Grade: Rough Machining: AC2000 / AC3000	Cast Iron AC500G (Coated) NS260C (Ceramic)	● Insert : Use UX Type Breaker ● Holder : Use Lever-lock Type
	Built-up Edge 	Tool Material Cutting Conditions	- Change to a grade which is more adhesion resistant. - Increase the cutting speed and feed. - Use cutting fluids.	Recommended Insert Grades : Cermet		
	Plastic Deformation 	Tool Material Cutting Conditions	- Change to high thermal resistant grades. - Reduce the cutting speed and feed.	Recommended Insert Grades : AC2000 or AC3000		

## ■ Analysis of Chip Control on Turning

### ● Classification Of Chip Formation & Their Influences

#### Shape Categories for Chips

Depth of Cut	A	B	C	D	E
Excess					
Slight					
Curled Length	No Curling	Over 50 mm	Up to and including 50 mm 1 to 5 Turns	Below 1 Turn	Half Turn
Remarks	Continuous Random Shape	Continuous Regular Shape	Good	Good	Excessively Broken Chip

- Good chip control : Types C and D
- Unsatisfactory chip control: -  
 Type A : Twines around the tool and work material, causes the machine to stop, quality impairment on the machined surface or problems in safety.  
 Type B : Causes performance reduction of the chip's automatic transfer system or even edge chipping.  
 Type E : Causes such troubles as spray of chips, unsatisfactory finished surface due to chattering, chipping of the cutting edges or increase in cutting resistance and heat generation.

#### Influence Of Chip Shapes

Influence	Chip Shape	Type A	Type B	Type C	Type D	Type E
		Tool life	Wear Resistance	O	O	O
	Chipping	X	X	O	O	X
Quality	Finished Surface	O	O	O	O	X
		O	O	O	O	X
Transfer	Machining Part Chips	X	O	O	O	O
		X	X	O	O	O
Power Consumption	Cutting Resistance Safety	O	O	O	O	X
		X	O	O	O	X
	Overall Evaluation	X	O	Excellent	Excellent	X

O: Superior X: Inferior

### ● Factors To Determine Chip Formation

(a) If Outlet Angle  $\eta = 0^\circ$

(b) If Outlet Angle  $\eta = 15^\circ$

- Factors: Outlet Angle and Cutting Direction
- Chip Forms According to The Combination of Factors

Cutting Direction	Outlet Angle	
	If $n = 0$	If $n \neq 0$
Upward Only	Cylindrical Form	Spiral Form
Sideways Only	Washer-Like Form	
Upward + Sideways	Conical Form	

### ● Types Of Chip Breaking

Figure of Chip Breaking	Type	Meanings
	Work Obstructive Type	- Cause by the effect of the upward curl only, if the rake is too small. - Chip broken because it struck against the work end face.
	Scroll Type	- Caused by the upward curling force when the rake angle is large. - Rolls in without breaking after striking against the work end face.
	Flank Obstructive Type	- Removed spirally by the mixing of upward and sideways curls. - Strikes against the flank and breaks.
	Side Curl Type	- Occurs if the sideways curling factor is superior. - Strikes against the flank of the tool and breaks.


### ● Formation Of Chips

	Flow Type	Shear Type	Tear Type	Crack Type
Form				
Condition	Continuous Chip and satisfactory surface finish	aA chip is sliced -off at the shear angle	Chip with the appearance of being torn off. The workpiece surface is damaged.	The swarf cracks before reaching cutting edge, which then separates it from parent work piece body.
Examples	Normal Cutting for Steels, Light Alloys, and Alloyed Cast Irons	Low speed cutting for Steels and Stainless Steels	Fine Cutting for Steels and Cast Irons at Excessively Low Speed	Cutting for General Purpose Cast Irons, Rocks, and Carbonous Materials
Influence	Large $\leftarrow$ Work Deformation $\rightarrow$ Small Large $\leftarrow$ Rake Angle $\rightarrow$ Small Slight $\leftarrow$ Depth of cut $\rightarrow$ Excess High $\leftarrow$ Cutting Speed $\rightarrow$ Low			

## Factors on Chip Control & Their Influences

### ● Influence On The Cutting Speed & Feed

- The effective range of the chip breaker is reduced with the cutting speed being increased.
- At high speeds and small feedrates, lengthened chips will result.
- At high speeds and large feedrates, packed chips will result.




Workpiece : S45C (Hs38)

Insert : SNMG120408N-UX  
Holder : PSBNR2525-43

Cutting Conditions:  
d = 3 mm

### ● Influence Of The Feed & Cutting Depth

- With small depths and small feeds, longer chips will be formed.
- With deeper depths and larger feeds, short chips will result.




Workpiece : S45C (Hs38)

Insert : SNMG120408N-UX  
Holder : PSBNR2525-43

Cutting Conditions:  
V = 150 m/min

### ● Influence Of The Nose Radius

- Chips become unsusceptible to breakage when the nose radius is larger and the cutting depth is less.
- Chips become thinner as the nose radius gets larger but their control is poor.





Workpiece : S45C (Hs38)

Insert : CNMG1204□□N-UX  
Holder : PCLNR2525-43

Cutting Conditions:  
V = 120 m/min  
f = 0.3 mm/rev

### ● Influence Of The Side Cutting Edge Angle

- If the side cutting edge angle becomes larger, the outlet angle and chips become larger and thinner respectively which makes the difficult to control.



Workpiece : S45C (Hs38)

Insert : SNMG120408N-UX  
Holder : PSBNR2525-43

(Side Cutting edge angle 15°)  
PSSNR2525-43  
(Side Cutting edge angle 45°)



Cutting Conditions:  
V = 150 m/min  
d = 3 mm

### ● Influence On The Rake Angle

- Chips become thicker when the rake angle gets smaller but they are easier to control.

For Small Top Rake Angle ( $\alpha_1$ )  
- The shear angle is small ( $\phi_1$ )  
- The chip is thick ( $t_1$ )

For Large Top Rake Angle ( $\alpha_2$ )  
- The shear angle is large ( $\phi_2$ )  
- The chip is thin ( $t_2$ )



# Milling Guidance


**M1 ~ M7**

<b>Milling Cutter Nomenclature &amp; Clamping Method</b> .....	<b>M2</b>
<b>Influences of Cutting Edge Geometries</b> .....	<b>M3</b>
<b>Surface Finish</b> .....	<b>M4</b>
<b>Cutter Size &amp; Number of Teeth</b> .....	<b>M5</b>
<b>Power Requirement, Cutting Conditions &amp; Grades Selection</b> .....	<b>M6</b>
<b>Trouble Shooting Guide for Milling</b> .....	<b>M7</b>

# Milling Guidance

## ■ Milling Cutter Nomenclature & Clamping Method

### ● Cutter Parts Name




### ● Clamping Method for Each Cutter Size

Cutter Body			Adaptor	
External Diameter D (mm)	Internal Diameter d (mm)	Chart	Type	Figure (See diagram below)
80	25.4	Chart 1	Arbor	Type A
100	31.75	Chart 2	Arbor	Type A
125	38.1	Chart 2	Arbor	Type A
160	50.8	Chart 2	Arbor	Type A
200	47.625	Chart 3	Centering Plug	Type B
250	47.625	Chart 3	Centering Plug	Type B
315	47.625	Chart 4	Centering Plug	Type B


#### Clamping Method :

##### Type A




#### Clamping Method :

##### Type B



### Cutter Body Configuration Diagrams




( D : External Diameter,  $D_1$  : External Diameter of Body,  $D_2$  : External Diameter of Boss, d : Hole Diameter, F : Height, E : Thickness, a : Width of Key Way, b : Depth of Key Way)

## ■ Influences of Cutting Edge Geometries


### ● Various Cutting Angles & Their Functions

	Description	Code	Functions	Influences
1.	Axial Rake Angle	A.R	Controls chip removal direction, effects adhesion of the chips and thrust force etc.	Rake angles can vary from positive to negative (large to small) with typical combinations of positive and negative, positive and positive or negative and negative configurations.
2.	Radial Rake Angle	R.R		
3.	Approach Angle	A.A	Controls chip thickness and chip removal direction	The effect of the large approach angle is to reduce the chip thickness and cutting force.
4.	True Rake Angle	T.A	Effective Rake Angle	<ul style="list-style-type: none"> <li>- With a positive (large) angle, cutting ability and adhesion resistance are improved but the strength of the cutting edge is weakened.</li> <li>- With negative (small) angle, the strength of the cutting edge is improved but chips will tend to adhere more easily.</li> </ul>
5.	Inclination Angle	I.A	Controls chip removal direction	- With a positive (large) angle, the chip removal is satisfactory with less cutting resistance but the strength of the corner is weaker.
6.	Wiper Flat Clearance Angle	F.A	Controls surface finish	A smaller clearance angle will produce a better surface finish.
7.	Clearance Angle		Controls edge strength, tool life and chattering, etc	

Ready Chart for True Rake Angles



Ready Chart for Inclination Angles



Example in using the above chart :

Given: A(Axial Rake Angle) = +10°  
 R(Radial Rake Angle) = -30°  
 C(Approach Angle) = 60°

Solution: T (True Rake Angle) taken from the chart is = -8°

**Formula:**  $\tan T = \tan R \cdot \cos C + \tan A \cdot \sin C$

Example in using the above chart:

Given: A(Axial Rake Angle) = -10°  
 R(Radial Rake Angle) = +15°  
 C(Approach Angle) = 25°

Solution: I (Inclination Angle) taken from the chart is = -15°

**Formula:**  $\tan I = \tan A \cdot \cos C - \tan R \cdot \sin C$

### ● Combinations Of Principal Angles & Their Features

	Negative - Positive Cutter	Double - Positive Cutter	Double - Negative Cutter
The effects of the various angle configurations with relation to chip formation and chip removal. A.R : Axial Rake angle R.R : Radial Rake angle A.A : Approach angle : Chip removal direction : Direction of cutter rotation	A.A (30~45°) 	A.A (15~30°) 	A.A (15~30°) 
Advantage	Best configuration for chip removal with good cutting action	Good Cutting Action	Economical using double sided inserts.
Disadvantage	Only single-sided inserts are available	Less Cutting Edge Strength Only single-sided inserts are available.	Poor Cutting Action
Applications	Suitable for Steels, Cast Irons Stainless Steels, Die Steels, etc.	General Milling of Steels Low rigidity workpiece	Milling of Cast Iron
Typical Cutter (Sample)	UFO Type	DPG Type	DNF Type
Chip forms Workpiece: SCM435 Condition : V = 130m/min f = 0.23 mm/tooth d = 3 mm			

## ■ Surface Finish

### ● Accuracy on Run-Out of teeth and Surface Finish


The cutting edges of a cutter with multiple cutting positions will inevitably have some slight deviations. This is defined as the accuracy or run-out of the teeth of which there are two kinds namely: the Axial Run-out of end cutting edges and Radial Run-out of peripheral cutting edges. Of these two the axial run-out of end cutting edges in particular is an influential factor of surface roughness.

#### a. Axial Run-Out of The End Cutting Edges

A difference between the maximum and minimum cutting edge positions projected in the axial direction when rotating with reference at the cutter center.


#### b. Radial Run-Out of The Peripheral Cutting Edges

A difference between the maximum and minimum cutting edge positions projected in the radial direction, when rotating with reference at the cutter center.



### ● Improving Run-Out of teeth:

1. Improve the dimensional tolerance of the inserts.
2. Improve the dimensional accuracy of the cutter body and its various components.




### ● Improving Surface Finish:

#### 1. Milling inserts with wiper flat

Projecting one of the inserts more than the others so as to act as a wiper.

- Inserts with Linear Wiper Flat (Face Angle: approx. 15°-1°)
- Inserts with Curved Wiper Flat (Curvature is about 500 mm in radius)



#### 3. Where No Wiper Inserts Are Available

Reposition inserts to achieve highest 2, 3 or 4 inserts equispaced around the cutter body so that each such high inserts can precede whatever number of lower inserts. Total feedrate/tooth should not be more than 80% of wiper flat width.

## ■ Cutter Size & Number of Teeth

### ● Selection of Cutter Size


#### 1. Engage Angle

Workpiece	Optimum Engage Angle	Ratio between the diameter of the cutter and the width of the workpiece
Steel	+20 ~ -10	3 : 2
Cast Iron	Below +50	5 : 4
Light Alloy	Below +40	5 : 3

The above recommendations are based on a  $\phi 150\text{mm}$  cutter of on a 100mm wide steel block.


#### 2. Mechanical Rigidity

Machine Horsepower	Adaptive Cutter Size
3-5 PS	80 ~ 100 mm
7.5-10 PS	100 ~ 160 mm
15-30 PS	160 ~ 200 mm



#### 3. Processing Time

It is more efficient to select a correct cutter diameter as time can be wasted waiting for the cutter to run off the workpiece if too large a diameter is used.




### ● Selecting The Number of Teeth

#### 1. Number of Simultaneous Cutting Edges

- The minimum number of cutting edges simultaneously engaged in the workpiece should be about 2-4 teeth.
- Less than this requirement will cause the work to shift due to impacts which may lead to insert failure or more inferior surface roughness.
- More than the requirement may cause deformation of the work, chattering and vibration.

#### - Relationship Between The Number of Simultaneous Cutting Edges and Cutting Force:



#### 2. Work Materials

Workpiece	Number of Teeth	Cutter example and the number of teeth
Steel	Dx1-1.5	UFO4160 (8 teeth)
Cast Iron	Dx2-1~Dx4	DHGF4160 (11 teeth)
Light Alloy	Dx1+α	APG4160 (8 teeth)

D: Nominal diameter of the cutter

#### - Considerations of Work Materials:

- Maximize the number of teeth for high feed milling of Cast Irons. (Rigidity of the machine and clamping must be sufficient.)
- For steels, the number of teeth should be reduced but feed per tooth should be increased. (Wide chip pockets and rigid cutter body are necessary)
- Improve the efficiency of milling non-ferrous alloys by increasing the speed.

#### - Examples Of The Combination Of Typical Cutters & Number Of Teeth

Application	Steel	Cast Iron	Light Alloy	High Feed
Cutter	UFO	DHGF	APG	DPV (Z)
Nominal Size				
100mm (4")	5	7	5	10
160mm (6")	8	11	8	18
200mm (8")	10	15	10	24
315mm (12")	14	23	16	36

#### 3. Other Conditions

1. For narrow workpieces, increase the number of teeth so that at least one tooth is always cutting.
2. When using unsteady machines and workpieces, the number of teeth should be reduced.

# Milling Guidance

## Power Requirement, Cutting Conditions & Grades Selection

### Power & Cutting Resistance

#### 1. Determination of Power Requirement

(Refer to the chart on the right)

$$W = \frac{Ps \times Q}{6.12 \times 10^3}$$

#### 2. Chip Removal

#### 3. Factors Influencing Cutting Resistance

Factor	Cutting Resistance will be ...
- If the inclination angle becomes large,	Reduced
- If the true rake angle becomes large,	Reduced
- If the cutting edge is excessively honed,	Increased
- If the approach angle becomes large,	Slightly Increased

#### - Determination Of The Power Requirement

#### - Determination Of Horse Power Requirement


$$H = \frac{W}{0.75}$$

W: Power Requirement (Kw)  
 H: Horsepower Requirement (HP)  
 Q: Chip Removal Amount (cm<sup>3</sup>/min)  
 L: Width of cut (mm)  
 F: Feed per minute (mm/min)  
 d: Depth of Cut (mm)  
 Ps: Specific Cutting Resistance  
 eg. Steel : 250-300  
 Cast Iron: 150  
 (Refer to chart on the right)

#### - Calculation Of Chip Removal Amount

$$Q = \frac{L \times F \times d}{1000}$$

#### - Specific cutting resistance based on feed in relation to the work material.



#### 4. Comparison of Cutting Resistance Among Typical SEC-ACE MILLS

Cutter Type	Edge angle			Cutting Resistance (kg)				Work : Alloy Steel (H <sub>B</sub> 250) Machine : Machining Center (15 HP) Conditions: V = 120m/min f = 0.3mm/tooth d = 3mm	
	A.R.	R.R.	A.A	0	50	100	150		
UFO	15°	-4°	45°	[Diagram showing force vectors]				Total Force	
APG	18°	-2°	25°	[Diagram showing force vectors]					Principal Force
DPG	8°	0°	15°	[Diagram showing force vectors]					

### Calculation Method of Cutting Conditions

#### - Calculation Of Cutting Speed


$$V = \frac{\pi \times D \times N}{1000}$$

#### - Calculation Of The Feed

$$F = f \times Z \times N$$

$$f = \frac{F}{Z \cdot N}$$

V: Cutting Speed (m/min)  
 π : 3.14  
 D: Cutter Diameter (mm)  
 N: Revolution (rpm)  
 F: Feed (mm/min)  
 f: Feed per tooth (mm/tooth)  
 Z: Number of Teeth




### Selection of Insert Grade

#### 1. Requirements:





- Good Wear Resistant eg. Coated grade
- Good Toughness eg. Tough carbide grade
- Good Resistance to Thermal cracks eg. Tough carbide grade
- Adhesion resistant eg. Cermet grade

#### 2. Recommended Insert Grade Depends on Work Material



## ■ Trouble Shooting Guide for Milling

### ● Suggested Remedies for Common Faults

Trouble		Basic Remedies		Proven Remedies																											
Edge Failure	<b>Excessive Flank Wear</b> 	Insert Grade Cutting Conditions	- Use more wear-resistant Grade.  Carbide P30 ---> P20 ---> Coated K20 ---> K10 ---> Cermet  - Decrease speed and increase feed.	- Recommended Insert Grade <table border="1"> <thead> <tr> <th></th> <th>Steel</th> <th>Cast Iron</th> <th>Light Alloy</th> </tr> </thead> <tbody> <tr> <td>Finishing</td> <td>T250A (Cermet)</td> <td>G10E (Carbide)</td> <td>DA2200(SumiDia)</td> </tr> <tr> <td>Roughing</td> <td>A30N (Carbide) AC230 (Coated)</td> <td>G10E (Carbide)</td> <td>EH20Z (Coated)</td> </tr> </tbody> </table>					Steel	Cast Iron	Light Alloy	Finishing	T250A (Cermet)	G10E (Carbide)	DA2200(SumiDia)	Roughing	A30N (Carbide) AC230 (Coated)	G10E (Carbide)	EH20Z (Coated)												
		Steel	Cast Iron	Light Alloy																											
	Finishing	T250A (Cermet)	G10E (Carbide)	DA2200(SumiDia)																											
	Roughing	A30N (Carbide) AC230 (Coated)	G10E (Carbide)	EH20Z (Coated)																											
<b>Excessive Crater Wear</b> 	Insert Grade Cutting Conditions	- Use more crater-resistant grade.  Carbide (K ---> M ---> P) ---> Cermet Coated  - Decrease speed and reduce take depth of cut and feed.	- Recommended Insert Grade <table border="1"> <thead> <tr> <th></th> <th>Steel</th> <th>Cast Iron</th> <th>Light Alloy</th> </tr> </thead> <tbody> <tr> <td>Finishing</td> <td>T250A (Cermet)</td> <td>G10E (Carbide)</td> <td>DA2200(SumiDia)</td> </tr> <tr> <td>Roughing</td> <td>AC230 (Coated)</td> <td>AC211 (Carbide)</td> <td>EH20Z (Coated)</td> </tr> </tbody> </table>					Steel	Cast Iron	Light Alloy	Finishing	T250A (Cermet)	G10E (Carbide)	DA2200(SumiDia)	Roughing	AC230 (Coated)	AC211 (Carbide)	EH20Z (Coated)													
	Steel	Cast Iron	Light Alloy																												
Finishing	T250A (Cermet)	G10E (Carbide)	DA2200(SumiDia)																												
Roughing	AC230 (Coated)	AC211 (Carbide)	EH20Z (Coated)																												
<b>Cutting Edge Chipping</b> 	Insert Grade Insert Design Cutting Conditions	- Use tougher grade.  Carbide P30 ---> P20 ---> P30 K01 ---> K10 ---> K20  - Use negative-positive edge type cutter with a large approach angle. - Reinforce the cutting edges (by honing).  - Reduce feed.	- Recommended Insert Grade : <table border="1"> <thead> <tr> <th></th> <th>Steel</th> <th>Cast Iron</th> <th></th> </tr> </thead> <tbody> <tr> <td>Roughing</td> <td>A30N (Carbide)</td> <td>G10E (Carbide)</td> <td></td> </tr> </tbody> </table> - Recommended Cutter : SEC-UFO Type					Steel	Cast Iron		Roughing	A30N (Carbide)	G10E (Carbide)																		
	Steel	Cast Iron																													
Roughing	A30N (Carbide)	G10E (Carbide)																													
<b>Partial Fracture of Cutting Edges</b> 	Insert Grade Insert Design Cutting Conditions	- Excessively low speed or feed, use a grade which is more adhesion resistant. - Thermal cracking, use a more thermal resistant grade. - Use negative-positive (or negative) edge type cutter with a large approach angle. - Enlarge the insert size (thickness in particular)  - Select conditions suitable to applications.	- Recommended Insert Grades : <table border="1"> <thead> <tr> <th></th> <th>Steel</th> <th>Cast Iron</th> <th></th> </tr> </thead> <tbody> <tr> <td>Finishing</td> <td>T250A (Cermet)</td> <td>G10E (Carbide)</td> <td></td> </tr> <tr> <td>Roughing</td> <td>AC325 (Coated)</td> <td>ACZ310 (Coated)</td> <td>EH20Z (Coated)</td> </tr> </tbody> </table> - Recommended Cutters : SEC-UFO Type - Insert Thickness : From 3.18mm to 4.76mm					Steel	Cast Iron		Finishing	T250A (Cermet)	G10E (Carbide)		Roughing	AC325 (Coated)	ACZ310 (Coated)	EH20Z (Coated)													
	Steel	Cast Iron																													
Finishing	T250A (Cermet)	G10E (Carbide)																													
Roughing	AC325 (Coated)	ACZ310 (Coated)	EH20Z (Coated)																												
Others	<b>Unsatisfactory Surface Finish</b>	Insert Grade Tool Design Cutting Conditions	- Use a more adhesion resistant grade. Carbide ---> Cermet - Improve axial run-out of the cutting edges. (Use cutter with less run-out on edges with proper setting of the inserts ) - Use wiper insert. - Use a special purpose cutter for finishing. - Increase speed.	- Recommended Cutters & Insert Grades : <table border="1"> <thead> <tr> <th></th> <th></th> <th>Steel</th> <th>Cast Iron</th> <th>Light Alloy</th> </tr> </thead> <tbody> <tr> <td rowspan="2">General Purpose</td> <td>Cutter</td> <td>UFO Type</td> <td>DHGF Type</td> <td>APG Type</td> </tr> <tr> <td>Insert</td> <td>T250A (Cermet)</td> <td>G10E (Carbide)</td> <td>EH20Z</td> </tr> <tr> <td>For Finishing Only</td> <td>Cutter</td> <td>PF Type</td> <td>PF Type</td> <td>APG Type</td> </tr> <tr> <td></td> <td>Insert</td> <td>T12A (Cermet)</td> <td>Ceramic Insert</td> <td>(With Wiper Chip) DA200 (SumiDia)</td> </tr> </tbody> </table>						Steel	Cast Iron	Light Alloy	General Purpose	Cutter	UFO Type	DHGF Type	APG Type	Insert	T250A (Cermet)	G10E (Carbide)	EH20Z	For Finishing Only	Cutter	PF Type	PF Type	APG Type		Insert	T12A (Cermet)	Ceramic Insert	(With Wiper Chip) DA200 (SumiDia)
			Steel	Cast Iron	Light Alloy																										
	General Purpose	Cutter	UFO Type	DHGF Type	APG Type																										
		Insert	T250A (Cermet)	G10E (Carbide)	EH20Z																										
	For Finishing Only	Cutter	PF Type	PF Type	APG Type																										
	Insert	T12A (Cermet)	Ceramic Insert	(With Wiper Chip) DA200 (SumiDia)																											
<b>Chattering</b>	Tool Design Cutting Conditions Others	- Use positive cutter with a large rake angle. - Use irregular pitched cutter. - Reduce feed. - Improve clamping of the workpiece and cutter.	- Recommended Cutters :  For Steel : UFO Type, EHG Type For Light Alloys : APG Type For Cast Iron : DHG Tyoe																												
<b>Unsatisfactory Chip Control</b>	Tool Design	- Use Negative (R.R)-Positive (A.R) Cutter - Reduce the number of teeth - Enlarge the chip pocket	- Recommended Cutters : UFO Type, EHG Type																												
<b>Edge Chipping on Workpiece</b>	Tool Design Cutting Conditions	- Enlarge the approach angle  - Reduce feed	- Recommended Cutters : UFO Type, EHG Type																												
<b>Burr on Workpiece</b>	Tool Design Cutting Conditions	- Use a positive cutter  - Increase speed	- Recommended Cutters : UFO Type, EHG Type																												

# Endmilling Guidance


**E1 ~ E10**

<b>Endmill Nomenclature</b> .....	<b>E2</b>
<b>Sumitomo's Endmills &amp; Cutting Conditions</b> .....	<b>E3</b>
<b>Cutting Profile &amp; Performance</b> .....	<b>E4</b>
<b>Cutting Profile &amp; Accuracy</b> .....	<b>E5</b>
<b>Performance Characteristics</b> .....	<b>E6</b>
<b>Cutting Fluid</b> .....	<b>E7</b>
<b>Features and Performance of PVD Coated Carbide Endmills</b> .....	<b>E8</b>
<b>High Speed Endmilling</b> .....	<b>E9</b>
<b>Trouble Shooting Guide for Endmilling</b> .....	<b>E10</b>


# Endmilling Guidance

## ■ Endmill Nomenclature

### ● Technical Terms




### ● Edge Shapes



## Sumitomo's Endmills & Cutting Conditions


### Sumitomo's Endmills

**- Solid Endmills**



1. Spiral Endmill - SSM,HHM,HHMR,SSHE
2. High Helix Endmill - HSM
3. Ballnose Endmill - SSB,SHB
4. Cermet Ballnose Endmill - SFB-T
5. Cermet Endmill - SFM-T
6. Tapered Endmill - STRM
7. Tapered Endmill - STM
8. Brazed Endmill - MES
9. Endmill for Graphite (Ballnose) - GBM
10. Endmill for Graphite (Square) - GSM

**- Indexable Type**



1. SEC-Repeater Wavemill - WRM
2. SEC-Wavemill - WEM
3. SEC-Multi Mill - UFO
4. SEC-Wavemill - WMM
5. SEC-Bore Endmill - HKE
6. SEC-ACE Ballnose Endmill - RBM 6000
7. SEC-Wavemill - WBMR
8. SEC-Wavemill - WBMR
9. SEC Helical Endmill - CMS
10. SEC Chamfering Endmill - SCP

### Calculation Of Cutting Conditions for Normal Endmills

#### 1. Cutting Conditions

#### 2. Feed

#### 3. Depth of Cut

### Calculation Of Cutting Conditions for Ballnose Endmills

#### 1. Boundary of Cutting

#### 2. Cutting Speed


#### 3. Feed

**- Calculation of Cutting Speed**

$$V = \frac{\pi \times D \times N}{1000}$$

$$N = \frac{1000 \times V}{\pi \times D}$$

Corner milling



V: Cutting speed  
 $\pi$ : 3.14  
 D: Endmill diameter (mm)  
 N: Spindle speed (rpm)  
 F: Feedrate (mm/min)  
 fr: Feed per revolution (mm/rev)  
 ft: Feed per tooth (mm/teeth)  
 Z: Number of teeth

**- Feed Calculation**

$$F = N \times fr$$


$$fr = \frac{F}{N}$$

$$F = N \times ft \times Z$$


$$ft = \frac{fr}{Z} = \frac{F}{N \times Z}$$

**- Depth of Cut**  
 Ad = Axial depth of cut  
 Rd = Radial width of cut


Grooving



**- Calculation of Boundary of Cutting**

$$D_1 = 2 \times \sqrt{2 \times R \times Ad} - Ad^2$$


**- Calculation of Speeds and Feedrate for the Ballnose endmills are the same as those for Normal endmills**




# Endmilling Guidance


## ■ Cutting Profile & Performance

### ● Cutting Directions

1. Up cut
2. Down cut



### ● Performance Comparison



### ● Chip Control

	SSM2080	SSM4080	KSM2080	SFM2080	HSM3080	
Corner Milling	Up Cut					
	Down Cut					
Grooving						

Work: Pre-hardened Steel (HRC40)  
 Cutting Conditions - Corner milling :  
 V = 25 m/min  
 f = 0.16 mm/rev  
 Ad = 12 mm  
 Rd = 0.8 mm

Cutting Conditions - Grooving:  
 V = 25 m/min  
 f = 0.05 mm/rev  
 Ad = 8 mm  
 Rd = 8 mm

## ■ Cutting Profile & Accuracy

### ● Precision


1. Bending of machined surface
2. Straightness
3. Roughness
4. Waviness
5. Displacement

Inclination of the center line

### ● Relation Between Cutting Condition and Bending of Machined Surface

Corner Milling					
Work: Pre-Hardened steel Condition: $V = 25 \text{ m/min}$ $A_d = 12 \text{ mm}$ $R_d = 0.8 \text{ mm}$					
		0.16 mm/rev		0.11 mm/rev	
Feed Direction		Up Cut	Down Cut	Up Cut	Down Cut
Cat. No.					
SSM2080					
SSM4080					
KSM2080					
SFM2080					
HSM3080					

Grooving					
Work: Pre-Hardened steel Condition: $V = 25 \text{ m/min}$ $A_d = 8 \text{ mm}$ $R_d = 8 \text{ mm}$					
		0.05 mm/rev		0.03 mm/rev	
Feed Direction		Up Cut	Down Cut	Up Cut	Down Cut
Cat. No.					
SSM2080					
SSM4080					
KSM2080					
SFM2080					
HSM3080					



# Endmilling Guidance

## Performance Characteristics

### Number of Teeth

Performance Condition	Performance Parameters	No. of teeth		
		2	4	
Tool Strength	Twist Rigidity	○	●	
	Bending Rigidity	○	●	
Surface Roughness	Roughness	○	●	
	Undulation	○	●	
	Bending of Machined Surface	○	●	
Tool Life S50C (HB200) ~ SKD11 (HB320)	Fixed Feed (mm/tooth)	Breakage Resistance	○	●
		Wear Resistance	○	●
	Fixed Efficiency	Breakage Resistance	○	●
		Wear Resistance	○	●
Cutting Range	Finishing	○	●	
	Light Cutting	○	●	
	Heavy Cutting	○	●	

●: Excellent ○: Good


Performance Condition	Performance Parameters	No. of teeth	
		2	4
Chip Control	Chip Packing	●	○
	Chip Removal	●	○
Boring	Counter Boring	●	○
	Surface Roughness	●	○
	Hole Expansion	●	○
Grooving	Chip Removal	●	○
	Groove Expansion	●	○
	Key Way Grooving	●	○
Cornering	Surface Roughness	○	●
	Chattering	●	○
Work Material	Alloy Steels	○	●
	Cast Irons	○	●
	Non-ferrous alloys	●	○
	Hard-To-Cut Materials	○	○

### Helix Angles


Helix Angle	Cutting Resistance			Surface Roughness			Tool Life			Catalogue No.
	Torque	Bending Resistance	Vertical Force	Roughness	Undulation	Bending of Machined Surface	Flank Wear	Peripheral Wear	Breakage	
30°	●	●	○	●	○	○	●	○	●	SSM 2000 / SSM 4000
60°	●	●	△	●	△	○	○	●	△	HSM 3000

●: Excellent ○: Good △: Fair

### Helix Angle and Cutting Force



### Flute Length



## ■ Cutting Fluid

### ● Features

		Lubricity	Adhesion Resistance	Infiltration	Cooling Effect	Rust Prevention	Smoking	Odour
Water Soluble Cutting Fluid	Emulsion type	○	△	○	●	△	●	○
	Soluble type	△	△	○	●	△	●	●
	Solution type	×	△	△	●	△	●	●
Non-water Soluble Cutting Fluid	Chlorinated oil	●	●	●	○	○	△	●
	Sulfo-chlorinated oil	●	●	●	○	○	△	△

### ● Cutting Fluid and Tool Life

#### Test Example:

Machine : Mazak V15  
 Work material : 1) Stainless Steel  
 2) Alloyed Steel  
 Tooling : SSM2050 (dia: 5 mm, 2 teeth, Helix angle: 30°)


Cutting Conditions: Cutting Speed: 30, 50, 70 m/min  
 Feedrate : 0.03 mm/rev  
 Depth of cut : Ad = 7.0 mm  
 Rd = 1.0 mm

Cutting Direction : Down cut  
 Cutting Fluid : Non-water soluble cutting fluid




#### Results

##### 1) Stainless Steel (H<sub>B</sub> 180)




##### 2) Die-mould Steel (HRC 48)




## ■ Features and Performance of PVD Coated Carbide Endmills


### ● Wide Range of Cutting Speeds



### ● Excellent Surface Roughness



### ● Optimum Machining for Hard-to-cut Materials



## High Speed Endmilling

### Performance Comparison by grade


A high speed cutting performance comparison between carbide, coated carbide and H.S.S endmills were conducted.  
 ( Note: At cutting speeds of over 70 m/min, an endmill with edge treatment is most efficient.)

#### Cutting Conditions


Work : SCM440 (HRC30)  
 Tool : SSM2080, SSM2080ZX,  
 H.S.S Tool (8 mm, 2 teeth)

Cutting speed (V)= 30, 50, 70, 100 m/min  
 Feedrate (f) = 0.04 mm/teeth  
 Depth of cut (d): Ad = 12 mm  
 Rd = 0.8 mm  
 Up cut, Water soluble fluid


#### • Cutting Force




#### • Bending of machined surface on work



#### • Surface roughness



#### • Tool Life



# Endmilling Guidance

## ■ Trouble Shooting Guide for Endmilling

### ● Standard Steps for Common Problems

Trouble		Basic Remedies		Details
Edge Failure	Excessive wear on periphery and end cutting edges	Tool material	- Use higher wear-resistant grades	- For solid endmills - change from uncoated to coated endmills eg. SSM-ZX type
		Cutting conditions	- Decrease speed and increase feed - Examine cutting fluids	- Cutting fluids - change from water soluble type to non-water soluble type.
	Chipping of the cutting edges	Cutting conditions	- Reduce feedrate - Use down-cut milling - Reduce the depth-of-cut	
		Machine and others	- Remove backlash on the machine - Stronger clamping of the workpiece - Reduce the amount of overhang	
	Tool breakage while cutting	Cutting conditions	- Increase speed - Decrease feedrate - Decrease depth-of-cut	- If the spindle speed is not fast enough, use an arbor speed inducer
		Tool	- Shorten the length of cut - Reduce the amount of overhang	
Unsatisfactory surface finish	Poor surface finish: - Surface roughness - Surface waviness - Surface squareness	Tool material	- Use materials that have a high Young's Modulus	- Use High-Helix Spiral Endmills (HSM type) - Change the endmill from 2 teeth to 4 teeth (ex. SSM2000 type change to SSM4000 type)
		Tool	- Enlarge the helix angle - Increase the number of flutes - Shorten the length of cut	
Cutting conditions	- Reduce feedrate - Reduce the depth-of-cut - Use up-cut milling			
Others	- Prevent build-up on the cutting edge			
	Chattering marks	Cutting conditions	- Decrease speed - Use down-cut milling - Use cutting fluid	- Check the clearances between the chuck, collet and endmill
		Others	- Ensure that both the workpiece and tool are properly secured	
Others	Packing of chips	Tool	- Reduce the number of flutes	- Change the endmill from 4 teeth to 2 teeth (ex. SSM4000 type change to SSM2000 type)
		Cutting conditions	- Reduce feedrate - Reduce the depth of cut	


# Drilling Guidance

D1 ~ D11

Twist Drill Nomenclature .....	D2
Comparison Table of Each Multidrill Type .....	D2
Varieties of Classification for Drills .....	D4
Machine Rigidity .....	D5
Clamping Selection .....	D6
Oil Coolant .....	D7
Hole Accuracy .....	D8
Relationship Between Hole Depth & Cutting Resistance .....	D9
Remarks on Using Longer Drills (KDS-DA, KDS-FA) .....	D10
Trouble Shooting Guide & Remedies for Twist Drills .....	D11


# Drilling Guidance

## Twist Drill Nomenclature



## Comparison Table of Each Multidrill Type

Characteristics & Consequences				MultDrill K Type	MultDrill P Type	MultDrill HK Type	MultDrill G Type	MultDrill A Type	MultDrill BA Type
1. Point Angle	150°	Small	Large	Small	●	●	●	●	●
	140°	↑	↑	↑					
	118°	Torque	Thrust	Burr					
2. Helix Angle	70°	Large	Small	Large					
	40°	Good	Bad	Small					
	30°	↑	↑	↑	●	●	●	●	●
3. Back Taper	25°	Cutting	Chip Flow	Twist Rigidity					
	10°	Bad	Good	Large					
	Big	Small	Few	Small	●	●	●	●	●
	↑	↑	↑						
	Cutting Resistance	Number of Regrinds	Many						
	↓	↓	↓						
	Small	Big							



## 4. Relief Angle

## 5. Web Thickness

## 6. Chisel Width


## 7. Flute Width Ratio

## 8. Edge Treatment Width


## 9. Edge Treatment Angle

Characteristics & Consequences				MultiDrill K Type	MultiDrill P Type	MultiDrill HK Type	MultiDrill G Type	MultiDrill A Type	MultiDrill BA Type
Relief Angle	15° 12° 10° 7°	Small Cutting Edge Large	Small Tool Wear Large	Large Run Out Stable	12° ~ 8°				
Web Thickness	30% 25% 20% 18% 10%	Large Thrust Small	Large Twist Rigidity Small	Strong Bending Resistance Weak	●	●	●	●	●
Chisel Width	Wide Narrow (Zero)	Large Thrust Small	Difficult Centripenance Easy	Weak Rigidity Strong	●	●	●	●	●
Flute Width Ratio	2.0 0.5	Small Twist Rigidity Large	Weak Bending Resistance Strong	Good Chip Removal Bad	●	●	●	●	●
Edge Treatment Width	Wide Zero	Large Cutting Resistance Small	Strong Strength of the edge Weak	●	●	●	●	●	●
Edge Treatment Angle	Big Zero	Large Cutting Resistance Small	Strong Edge Strength Weak	●	●	●	●	●	●

### Minimum Relief Angle




### Web Thickness and Thrust (Effect of the Thinning)





The thinning makes concentrating thrust small. This means easy cutting, good chip removal and longer tool life.

### Small Chisel Width by the Thinning (Thinning Example)



S Type: Standard web thinning  
N Type: Mainly on thinner webs  
X Type: For hard-to-cut material and deep holes

### Edge Treatment Width & Cutting Resistance



Drill: MultiDrill KDS215MA  
Edge Treatment Width: ●:0.15 mm △:0.23 mm  
Work: S50C (HB230)  
Cutting Conditions: V = 50 m/min  
Water Soluble Oil

# Drilling Guidance

## ■ Varieties of Classification for Drills

### 1. Classification According to Type

### 2. Classification According to Shank Configurations

### 3. Classification According to The Length

### 4. Classification According to The Helix Angle

### 5. Classification According to Profiles

### 6. Classification According to Functions and Applications

### 7. Classification According to Materials of The Cutting Portion

No.	Type	Descriptions	Illustrations
1	Solid Drill	A drill which is wholly composed of the same material eg. hard alloys.	(1)
2	Solid Carbide-End	A drill which has a carbide portion of a defined length brazed to its tip.	(2)
3	Tipped Drill	A drill that has brazed carbide tips.	(3)
4	Throw-Away Tipped Drill	A drill which uses throw-away inserts which are mechanically clamped on its tip.	(4)
5	Straight Shank Drill	A drill with a cylindrical formed shank. (There are also straight shank drills with tenon or threaded drivers.)	(5)
6	Taper Shank Drill	A drill with a Morse taper shank. (There are also threaded morse taper shank drills.)	(6)
7	Stub Drill	A drill with a much shorter overall length as compared to a normal drill of the same diameter.	(7)
8	Regular Length Drill	A drill with a standard market length.	(8)
9	Long Drill	A drill with a longer overall length as compared to a normal drill of the same diameter.	(9)
10	Twist Drill	A drill with left or right handed flutes twisting along the length of its body.	(10)
11	Straight Fluted Drill	A drill with no twists in its flutes.	(11)
12	Oil Hole Drill	A drill with through-tool coolant holes.	(12)
13	Sub-land Step Drill	A drill with two diameter sizes with an individual flute for each diameter size.	(13)
14	Double Margin Drill	A drill with two fluted lands.	(14)
15	Flat Drill	A straight fluted drill with a plate-like cutting portion.	(15)
16	Step Drill	A drill designed to perform step drilling or to produce a countersunk hole.	(16)
17	Core Drill	A drill which has no center point cutting but is used for finishing or reaming of pre-drilled holes.	(17)
18	Center Drill	A drill is used for making pilot holes.	(18)
19	Gun Drill	A long drill used on a special machine for drilling of very long holes.	(19)
20	Spade Drill	A straight fluted drill having a plate-like formed cutting portion, usually mechanically held infixed to the body.	(20)
21	Pivot Drill	A drill with its diameter size different from its shank diameter.	(21)
22	Micro Drill	A small sized drill used to drill circuit boards for electronic equipment.	(22)
	● High Speed Steel Drill	A drill made wholly out of H.S.S. material.	eg. SKH9, SKH55, M7, M33, etc
	● Carbide Drill	A drill made wholly out of Carbide material.	eg. Carbides - K10 & K20, ultra-corpuscle alloys etc.
	● Coated Drill	The above-mentioned drills with coating	eg. Corresponding to our Multidrills
	● Others	A drill with either a sintered CBN or PCD drill tip.	eg. Corresponding to our SumiDia drills.

## Machine Rigidity

### Machine Capacity



#### 1. Power Consumption & Thrust Formula for Multi Drills

$$\text{Power Consumption} = (H_b \times D^{0.68} \times V^{1.27} \times f^{0.59}) / 36000$$

$$\text{Thrust} = 0.24 \times H_b \times D^{0.68} \times f^{0.61}$$



Power Consumption (kW)    H<sub>b</sub>: Brinell Hardness    V: Velocity (m/min)  
 Thrust (kg.f)                      D : Drill Diameter                      f : Feedrate (mm/rev)

On the designing the machine, please multiply 1.6 on Power Consumption and 1.4 on Thrust.



Work: S48C (H<sub>b</sub>220)  
Speed: 50m/min

#### 2. Power Consumption & Thrust Formula for WDS-Drill




Work: SCM440 (H<sub>b</sub>220)  
Speed: 100m/min

### Spindle

When using above chart, please consider the motor power and machine rigidity especially during high efficiency drilling (high thrust) where it requires high rigidity of the spindle. Although it is important to consider the horsepower requirements, the structure and of the main spindle axle is also an important factor for considerations. In general machining centres, rigidity of the machine's configuration are as specified:

- 1) BT50 > BT45 > BT40
- 2) single axle > plural axle



### Clamping

As high efficiency drilling enhances a large horizontal cutting force in addition to large thrust and torque forces, it is therefore essential to have a rigid and stable clamping.

# Drilling Guidance

## ■ Clamping Selection


### 1) External Coolant

**1) Deflection Accuracy**  
**2) Rigid Clamping**  
 Both are very important factors for carbide drilling, it is therefore important to select a suitable clamping system as recommended below.

Spindle Head									
Drill Shank	Tapered		Straight		Straight with Tang		Straight with Flat face		
Chucking	Tapered Holder	Taper Holder Sleeve	Milling Chuck	Collet Holder	Drill Chuck	QC Type stub holder	Taper Holder Sleeve	Side Lock Holder	
Drill	Brazed Carbide-Tipped Drill	●	○	●	●	×	●	○	●
	MultiDrill (Type K,P,G)	×	×	●	●	×	●	×	●
	MultiDrill (Type A,FA)	○	×	●	●	×	○	×	●
	Economical Solid Carbide Drill	×	×	●	●	○	○	×	×

○:Excellent ●:Good ×:Poor

### 2) Internal Coolant



### 3) Correct Operation



## Oil Coolant

### 1. Selection Of Oil

To maximise the hole accuracy and tool life, the most suitable cutting fluid for **MULTI DRILLS** is non-water soluble (neat) cutting oil but one must be careful about the development of smoke and fire. Please supply in adequate volume. Neat oil is not suitable at high speeds. ( $V > 40$  m/min).

At high speeds, the most suitable cutting fluid is water-emulsifiable, high density oil. (7-10 times dilution.)

Soluble oil and Chemical fluids are not recommended.

### 2. Features

		Lubricity	Adhesion Resistance	Permeability	Cooling Capability	Rust Resistance	Smoke Retardant	Odor
Water Soluble Oil	Emulsifiable Oil	○	△	○	●	△	●	○
	Soluble Oil	△	△	○	●	△	●	●
	Solution Oil	×	△	△	●	△	●	●
Non Water Soluble Oil	Chlorinated Oil	●	●	●	○	○	△	●
	Sulfo-Chlorinated Oil	●	●	●	○	○	△	△

### 3. Oil Supply

**Internal**

Higher oil pressure and large amounts of oil are desirable.  
Min. pressure is 3-5 kg/cm<sup>2</sup>.  
Min. volume is 2-5 l/min.

**External Vertical**

**Horizontal**

### 4. Examples

Work	Drill	Machine Conditions	Results		Remarks
			Efficiency	Life	
Brake Hose Part Low Carbon Steel (H <sub>s</sub> 150-160) 	MDS110SK Dia. 11mm	NC Lathe V=66m/min f=0.35mm/rev	Multi Drill V=66 f=0.35  HSS coated V=41 f=0.25	5,000 pcs./reg (55m) 750 pcs./reg (13.5m)	-Productivity was 2.2 times higher -Tool life was 6.7 times higher - Good hole accuracy which can omit reaming process
Construction Machine Part Low Carbon Steel (H <sub>s</sub> 150) 	KDS240LA Dia. 24mm	Machining Centre V=65m/min f=0.35mm/rev	Solution Oil 170 holes Emulsifiable Oil 270 holes		-1.6 times tool life by using emulsifiable oil
Machine Part Alloy Steel (H <sub>s</sub> 280) 	KDS194LA Dia. 19.4mm	NC Lathe V=60m/min f=0.25mm/rev	Dilution Rate 30 Times 100 Hole 10 Times 185 Hole		-10 times dilution is good. -5 times may be too dense

# Drilling Guidance

## ■ Hole Accuracy

### 1) Selection of the Drill Diameter


The chart below shows the actual expansion of the hole diameter for various types of materials, please consider these expansion when selecting a drill.

Drill	Soft Steel	General Steel Alloy Steel	Ductile Cast Iron	Cast Iron	Aluminium
MDS Type	+20 ~ +50	0 ~ +30	0 ~ +40	0 ~ +40	-10 ~ +40
KDS Type	+20 ~ +70	+30 ~ +80	+10 ~ +50	+10 ~ +50	0 ~ +40


Example : If you want to drill a hole of diameter 13.1 ~ 13.15 on soft steel, the drill diameter to be selected should be  $\phi 13.10$  (MDS131MP)

### 2) Run-Out of the Drill

Run-out of the drill at the edge and near the center are important.




A: Difference after thinning  
B: Lip Height Difference



### 3) Deflection Accuracy (Tool rotating)

The run-out of the drill after chucking should be within 0.03mm.

The big run-out will cause oversized holes and when used on a machine with low rigidity, it may cause drill breakage.




Run Out (mm)	Hole Oversize		Draft Force	
	0	0.05 (mm)	0	10 (kg)
0.005	Short bar	Short bar	Short bar	Short bar
0.09	Long bar	Long bar	Long bar	Long bar

MDS120MK Carbon Steel (Hc230)  
V=50m/min, f=0.3mm/rev, depth=38mm


### 4) Deflection Accuracy (Work rotating)

On a lathe, the run-out at both positions (A) and (B) should be within 0.03mm.



### 5) Uneven Work Surfaces

If the surface of the workpiece is not flat at the entrance and exit points, the feedrate should be reduced to about 0.1~0.5 mm/rev.



## Relationship Between Hole Depth & Cutting Resistance

- Control the Cutting Resistance

Chip removal is very difficult in one-pass deep hole drilling. Clogged chips in the flute makes cutting forces higher and it may lead to drill breakage.

### Solution by Flute Design

	Conventional Design	Deep Hole Application	Drill size: $\phi 20\text{mm}$ Material : High Carbon Steel Conditions: $V = 60\text{m/min}$ $f = 0.25\text{mm/rev}$ $d = 140\text{mm}$
Horse Power (KW)			
Design			

### Solution by Step-Feed

		Normal Drilling	Step Feed [Type 1]	Step Feed [Type 2]	Drill : MDS080MK Material : High Carbon Steel Conditions: $V = 50\text{m/min}$ $f = 0.25\text{mm/rev}$ $d = 38\text{mm}$
Cutting Resistance	Torque				
	Thrust				
Drill path					


Step-feeding has two objectives: 1) Chip formation and 2) chip removal.

Low speed drilling by HSS, solid carbide or twist drills requires step-feeding [Type 2] to ease chip removal. Conversely, high speed drilling with MultiDrills requires step-feeding [Type 1] to assist in chip formation.


## ■ Remarks on Using Longer Drills (KDS-DA, KDS-FA)

### ● Problem

High speed cutting with longer sized drills leads to the deflection of the drill, bending of drilled hole and drill breakage.



### ● Two Solutions



## ■ Trouble Shooting Guide & Remedies for Twist Drills

### ● Standard Step for Common Problems

	Trouble	Basic Remedies		Proven Remedies
Drill Failures	Excessive Wear of the Cutting Edge	Tool Conditions Cutting Fluid	<ul style="list-style-type: none"> <li>- Enlarge the clearance angle.</li> <li>- Use higher wear-resisting tool material.</li> <li>- Set the correct cutting speeds.</li> <li>- Use more efficient cutting fluids with high lubricity.</li> </ul>	<ul style="list-style-type: none"> <li>- Clearance angle of 10°~12° for steels</li> <li>- Change to PVD-coated MultiDrills</li> <li>- Change to emulsifiable type coolant, higher viscosity for heavy duty drilling</li> </ul>
	Chisel Point Chipping	Tool Conditions Cutting Fluid	<ul style="list-style-type: none"> <li>- Machine correct the web thinning and honing.</li> <li>- Shorten the overall length of drill and overhang.</li> <li>- Reduce the feedrate (more on entry).</li> <li>- Change to correct cutting fluid.</li> </ul>	<ul style="list-style-type: none"> <li>- Water-soluble fluid for heavy duty drilling (Emulsifiable Type)</li> </ul>
	Chipping of Peripheral Cutting Edge	Tool Conditions Cutting Fluid	<ul style="list-style-type: none"> <li>- Increase edge honing.</li> <li>- Decrease cutting speed.</li> <li>- Reduce feed during entrance or break-through.</li> <li>- Change to correct cutting fluid with a minimum of 5 bars pressure.</li> </ul>	<ul style="list-style-type: none"> <li>- Water-soluble fluid for heavy duty drilling (Emulsifiable Type)</li> </ul>
	Deposition, Wear of Margin Part	Tool Cutting Fluid Others	<ul style="list-style-type: none"> <li>- Slightly enlarge the back taper on diameter.</li> <li>- Narrow the width of margin</li> <li>- Supply cutting fluids sufficiently minimum of 5 bars</li> <li>- Early regrinding</li> <li>- Direction of coolant supply should be correct</li> </ul>	<ul style="list-style-type: none"> <li>- Water-soluble fluid for heavy duty drilling (Emulsifiable Type)</li> </ul>
	Fracture of Drill Body	Tool Conditions Cutting Fluid Others	<ul style="list-style-type: none"> <li>- Use a more rigid drill.</li> <li>- Slightly enlarge the back taper on diameter and narrow the margin width.</li> <li>- Decrease the cutting speed and feedrate.</li> <li>- Increase the coolant flow rate to min 5 bars.</li> <li>- Avoid packing of chips by pecking.</li> <li>- Increase rigidity of the machine.</li> <li>- Increase clamping rigidity of the work.</li> </ul>	<ul style="list-style-type: none"> <li>- Use MultiDrill K Types</li> <li>- Increase the number of pecks per cycle</li> </ul>
Unsatisfactory Working Accuracies	Excessive Over-Sized Holes	Tool Conditions Cutting Fluid	<ul style="list-style-type: none"> <li>- Correctly grind the point configuration.</li> <li>- Decrease the cutting speed and feed.</li> <li>- Reduce the oil pressure and flow rate.</li> </ul>	<ul style="list-style-type: none"> <li>- Eliminate the eccentricity of the chisel edge</li> <li>- Minimise the difference between lip heights (within 0.02 mm)</li> </ul>
	Poor Surface Finish	Tool Conditions Cutting Fluid	<ul style="list-style-type: none"> <li>- Increase rigidity of the machine.</li> <li>- Increase the cutting speed when built-up edge occurs.</li> <li>- Adjust the feedrate proportionally.</li> <li>- Supply sufficient cutting fluids.</li> </ul>	<ul style="list-style-type: none"> <li>- Use Multi Drill K Type</li> <li>- Use sulfurised oil as the cutting fluid</li> </ul>
	Drill Wondering	Tool	<ul style="list-style-type: none"> <li>- Eliminate the eccentricity of right and left cutting lips.</li> <li>- Correct deflection and run-out of the drill</li> </ul>	<ul style="list-style-type: none"> <li>- Minimise the difference between lip heights (within 0.02 mm)</li> <li>- Use the guide bush (not suitable for MultiDrills)</li> </ul>
Unsatisfactory Chip Control	Packing of Chips	Conditions Cutting Fluid	<ul style="list-style-type: none"> <li>- Introduce peck-drilling.</li> <li>- Decrease speed and increase feedrate.</li> <li>- If through-tool coolant system is used, increase the coolant pressure and flow rate.</li> </ul>	
	Stringy Swarf	Conditions	<ul style="list-style-type: none"> <li>- Decrease the cutting speed.</li> <li>- Increase feedrate.</li> </ul>	
Others	Chattering During Drilling	Tool	<ul style="list-style-type: none"> <li>- Reduce the clearance angle.</li> <li>- Use a more rigid drill.</li> </ul>	<ul style="list-style-type: none"> <li>- Change to MultiDrill K Type</li> </ul>

# Exotic Materials Guidance

**X1 ~ X8**

Insert Grades & Cutting Conditions for Exotic Materials .....	X2
Application Examples.....	X4
Machinability of Hard to Cut Materials.....	X6
Machining of Stainless Steel .....	X7
Cutting Quench-Hardened Steels.....	X8

# Exotic Materials Guidance

## ■ Insert Grades & Cutting Conditions for Exotic Materials

### ● Turning

[  Cutting Speed (V) : m/min,  Feed rate (f) : mm/rev ]

Work Materials		General Machining and Roughing			Finishing		
Type	Examples	Recommended Insert Grades	V f		Recommended Insert Grades	V f	
Stainless Steels	SUS410	AC3000 AC304 EH10Z (Coated)	V f	100 180 0.2 0.6	T110A (Cermet)	V f	120 250 0.1 0.2
	SUS304	AC3000 AC304 EH10Z (Coated)	V f	80 160 0.2 0.6	EH20Z (Coated)	V f	100 200 0.1 0.2
Nickel Alloys	Inconel 718	EH20Z (Coated)	V f	30 50 0.05 0.25	BN600 (CBN)	V f	50 200 0.05 0.15
	Inconel 718	EH10Z (Coated)	V f	20 40 0.1 0.3	BN600 (CBN)	V f	50 200 0.05 0.15
	Hastelloy B	EH10Z (Coated)	V f	30 50 0.1 0.3	BN600 (CBN)	V f	50 150 0.05 0.15
	Nimonic 80A	EH10Z (Coated)	V f	30 50 0.1 0.3	BN600 (CBN)	V f	50 150 0.05 0.15
Cobalt Alloys		EH10Z (Coated)	V f	20 60 0.1 0.2	BN600 (CBN)	V f	100 200 0.05 0.15
Ferrite Alloys		AC2000 (Coated)	V f	30 60 0.1 0.3	BN600 (CBN)	V f	100 200 0.05 0.15
Pure Titanium		EH10Z (Coated)	V f	30 60 0.1 0.3	BN600 (CBN)	V f	100 200 0.1 0.2
Titanium Alloys	Ti-6Al-4V	EH10Z (Coated)	V f	20 50 0.1 0.3	BN600 (CBN)	V f	100 200 0.05 0.15
Stellite		EH10Z (Coated)	V f	20 60 0.1 0.2	BN600 (CBN)	V f	70 150 0.05 0.15
Shape Memory Alloy		EH10Z (Coated)	V f	20 50 0.05 0.15	BN600 (CBN)	V f	50 100 0.05 0.15
Heat Resistant Sintered Alloys (Valve Seat Ring)		EH10Z (Coated)	V f	30 70 0.05 0.15	BNX4 (CBN)	V f	50 150 0.05 0.15
Quench Hardened Steels	Hardened Blister Steels (Over HRC55)	EH10Z (Coated)	V f	50 150 0.05 0.1	BNX20 BN250 BN300 (CBN)	V f	50 150 0.05 0.2
High Manganese Steels	SCMnH3	NB90S (Ceramics)	V f	50 150 0.1 0.3	BNX20 BN250 BN300 (CBN)	V f	100 300 0.02 0.2
Carbide	85WC-15Co	EH10Z (Coated)	V f	10 30 0.05 0.2	DA90 (PCD)	V f	10 30 0.05 0.2
FRP	CFRP Carbon Fiber Reinforced Plastic	EH10Z (Coated)	V f	—	DA150 (PCD)	V f	150 300 0.05 0.2

## ● Milling

[ — Cutting Speed (V) : m/min, — Feed rate (f) : mm/t ]

Work Materials		Recommended Tools		Recommended Cutting Conditions					
Type	Example	Cutter Type	Grades	V	20	50	100	200	400
				f	0.02	0.05	0.1	0.2	0.4
Stainless Steels	Hot Rolled Stainless Steel Strips (AISI)	UFO-Type	T130Z (Coated Cermet) AC325 (Coated Carbide)	V			160	220	
				f			0.15		0.4
Nickel Base Heat Resistant & Corrosion Resistant Materials	Inconel 718	GRC-Type	EH20(Z) (K10 Coated Carbide)	V	20	50			
				f			0.1	0.2	
Titanium Alloys	Ti6Al-4V	GRC-Type	EH20(Z) (K10 Coated Carbide)	V	20	50			
				f			0.1	0.2	
Quench Hardened Steels	SKD61	Sumiboron Facemill BNM-Type	BN250 (CBN)	V			100	200	
				f		0.05		0.15	
High Manganese Steels	SCMnH3	UFO-Type	A30N (P30 Carbide)	V		40	80		
				f			0.15	0.3	

## ● EndMilling

[ — Cutting Speed (V) : m/min, — Feed rate (f) : mm/rev ]

Work Materials		Recommended Tools		Recommended Cutting Conditions					
Type	Example	Endmill Type	Grades	V	20	50	100	200	400
				f	0.02	0.05	0.1	0.2	0.4
Stainless Steels	Hot Rolled Stainless Steel Strips (AISI)	Coated Solid Spiral Endmill SSM-ZX Type	Coated Carbide	V		30	70		
				f	0.015		0.05		
Nickel Base Heat Resistant & Corrosion Resistant Materials	Inconel 718	High Lead Coated Endmill HSM-ZX Type	Coated Carbide	V	20	40			
				f	0.015		0.05		
Titanium Alloys	Ti6Al-4V	Coated Spiral Endmill SSM-ZX Type	Coated Carbide	V		30	70		
				f	0.015		0.05		
Quench Hardened Steels	Alloy Tool Steels (AISI)	Sumiboron Endmill BNES-Type BNBS-Type	BNX3 (CBN)	V		30	150		
				f	0.015		0.05		

## ● Drilling








[ — Cutting Speed (V) : m/min, — Feed rate (f) : mm/rev ]

Work Materials		Recommended Tools		Recommended Cutting Conditions					
Type	Example	Drill Type	Grades	V	20	50	100	200	400
				f	0.02	0.05	0.1	0.2	0.4
Stainless Steels	Stainless Steel Wires (AISI)	MultiDrill HK-Type MultiDrill K-Type MultiDrill A-Type	ZX Coated ZX Coated Coated	V	20	70			
				f	15	30		0.1	0.3
							0.1	0.3	







# Exotic Materials Guidance

## Application Examples

### Turning

	Application	Work	Tool	Cutting Conditions	Results
		1) Part Name 2) Materials	3) Tool Name 4) Grade	V = Speed f = Feed d = Depth of Cut	
Stainless Steels		1) Valve Parts 2) SUS304	3) CNMG120408N-UP 4) AC3000, AC304	V = 90-110 f = 0.25 d = 2.5-3.5	Smoother cut and superior chip-control than conventional chip breakers
		1) Seat Ring 2) SUS304	3) CNMG120408N-UP 4) AC3000, AC304	V = 100 f = 0.25 d = 4-5	Superior anti-notch wear and better chip control than conventional chip breakers
Hastelloy	1) Aerospace Parts 2) Nimonic 75 (Ni60%, Cr20%, Co, C, etc) Exotic Materials (Co20%, Cr20%, Ni47%)		3) CNMG120408N-UP 4) EH20Z	V = 45 f = 0.15 d = 0.25	Wear resistance and chip control is superior as compared to the competitor's
Titanium Alloys		2) Titanium Alloy (Ti-6Al-4V)	3) SNMG120408N-UP 4) EH10Z EH20Z (K10 Coated Carbide)	V = 30 m/min f = 0.15 mm/rev d = 1.0 mm Wet (Water Soluble)	
Stellite		1) Valve 2) Combination of Hot Rolled Stainless Steel Strips (AISI) and stellite	3) CNMG120408N-UG 4) EH10Z	V = 20-40 m/min f = 0.1 mm/rev d = 1-2 mm Dry	EH10Z: 5 pcs/corner Competitor's K10 Carbide: 2 pcs/corner  (EH10Z grade gives a smoother cut and good surface finish on both stellite and stainless parts)
P/M Sintered Alloys		1) Valve Seat 2) P/M Sintered Alloy	3) Special Holder (Carbide Shank) 4) BNX4 (CBN)	V = 56 m/min f = 0.1 mm/rev d = 0.3 mm Wet	Tool Life of BNX4 is twice that of competitor's CBN grade
Quench Hardened Steels		1) Crank Web Pin Hole 2) JIS S48C (HRC55-62)	3) SumiBoron Insert SPGN090312 4) BN250	V = 90 m/min f = 0.07 mm/rev d = 0.15 mm Wet	Tool Life: 400 pcs Surface Finish: 3-4 μm (Rmax) Diameter Compensation: 100 pcs each
Inconel 718		1) Aircraft Part 2) Inconel 718	3) CNMG190612N-MU 4) EH10Z	V = 40 m/min f = 0.15 mm/rev d = 1.5 mm	
Carbide		1) Round bar 2) Carbide G6	3) SumiDia Insert SNGN120408 4) DA90 (PCD)	V = 10 m/min f = 0.065 mm/rev d = 0.05 mm Dry	Machining time per regrind is approx 20 minutes

## ● Milling

	Tool Selection and Work Application (mm)	Work Materials	Tools	Cutting Conditions	Results
		1) Part Name 2) Materials	3) Cutter Cat. No. 4) Insert Cat. No. (Grade)	V = Cutting Speed f = feed/tooth d = Depth of Cut	
Stainless Steels		1) Machine Tool Parts 2) Casted Stainless Steel	3) UFO4160R 4) SFEN12T3AZTN (AC325)	V = 176 m/min N = 350 rpm F = 550 mm/min f = 0.2 mm/tooth d = 2 mm	Efficiency is 220% higher when compared to conventional cutters with 25° posi-inserts  Very stable machining without chattering and chipping of the cutting edges.
Inconel		1) Thin Structural Work 2) Inconel 625	3) GRC6160R 4) RGEN2004SN (EH20)  Competitor's Cutter: ø160 mm (Coated Inserts)	V = 40-50 m/min f = 0.2-0.3 mm/tooth d = 3-5 mm  Competitor's Cutter V = 20 m/min f = 0.25 mm/tooth d = 5 mm	Our cutter performed for over 35 minutes  Initially there were sparks and after 20 minutes, the competitor's inserts were totally broken.
—		1) Plate 2) MONEL 400	3) UFO4100R 4) SFEN12T3AZTN (AC325)	V = 250 m/min N = 796 rpm F = 498 mm/min f = 0.125 mm/tooth d = 5 mm Wet	Using a cutter with 15° posi round-insert is difficult because the chips adhere to the cutting edge.  As the rake angle of UFO is much higher and performance of chip exhaust is superior, they get 370% higher efficiency.
Titanium Alloys		1) Block 2) Titanium-Alloy (Ti-6Al-4V) HRC36~40	3) GRC6160R 4) RGEN2004SN (EH20)	V = 30 m/min f = 0.2 mm/tooth d = 3-4 mm	Performed for over 40 minutes.
Titanium Alloys	—	1) ---- 2) Ti-6Al-4V (HRC32~34)	3) UFO4160R 4) SFEN12T3AZTN (EH20Z)	V = 54 m/min N = 113 rpm F = 181 mm/min f = 0.2 mm/tooth d = 2.5 mm	As compared with G10E grade inserts, the Z-coated inserts provided 170% higher efficiency and 200% longer tool life.
Die Steels		1) Block 2) SKD11	3) UFO4063ER 4) SFKN12T3AZTN (AC325)	V = 200 m/min N = 1010 rpm F = 1000 mm/min f = 0.2 mm/tooth d = 0.8 mm 2 pass/area	Even when machining the forged surface, the UFO cutter cuts smoothly and provides a good surface finish.
		1) Forging Die Part 2) HAP72 (HRC40)	3) UFO4100R 4) SFEN12T3AZTN (A30N)	V = 182 m/min N = 580 rpm F = 305 mm/min f = 0.11 mm/tooth d = 3 mm	Machining was impossible using 15° or 20° posi-insert cutters but with UFO cutter, there was no problem under these conditions.

# Exotic Materials Guidance

## ■ Machinability of Hard to Cut Materials

< Machinability >

- Machinability Denotes ....

Machinability and Machining of hard-to-cut Materials:

- 1) Less cutting tool failures and longer tool life
- 2) Smaller cutting resistance and power consumption
- 3) Satisfactory finishing of products
- 4) Satisfactory chip control

## ● Machinability Index


- An index designed in the U.S.A. in which machinability is expressed by taking notice of the tool life only.
- Machinability is numerically shown and therefore it is used as the standard to determine suitability of cutting.
- The material becomes difficult to cut as the numeric value decreases. 45 and below is designated as hard-to-cut-work material.

## ● Machinability Index Of Typical Materials


Workpiece		Machinability Index	Workpiece		Machinability Index	Workpiece		Machinability Index	
Copper Alloy		100 ~ 70	Stainless Steel	Ferritic	65 ~ 50	Heat and Corrosion Resisting Alloys	Fe Base	A-286	30 ~ 10
Steel	Mild	85 ~ 70		Martensitic	55 ~ 40		Ni Base	Inconel 901	16 ~ 6
	Medium	65 ~ 50		Austenitic	50 ~ 35		Inconel 901		
	Hard	60 ~ 50		Alloy Tool Steel	30 ~ 25		Cr Base	L-605	15 ~ 6
Low Alloy Steel		65 ~ 50	High Manganese Steel	40 ~ 30	Stellite 21				
Cast Iron		70 ~ 50	Titanium Alloy	30 ~ 20					

## < Problems Of Hard To Cut Materials & Remedies >

### ● For Heat and Corrosion Resistant Alloys



### ● For Hardened Materials (Quench-Hardened Steels, Carbides, etc)



### ● Common Considerations For Cutting Hard-to-Cut Work Materials

- Machines : All backlash should be eliminated with exceptional axial rigidity.
- Tools : Use a larger shank size and minimise the overhang to increase rigidity.
- Workpiece : Assure fittings and protection from run-out and chatter.

## ■ Machining of Stainless Steel

### ● Classification & Properties

Classification	Alias	Material (JIS)	Machinability	Machinability Index	Quench Hardened	Magnetism	Typical Applications
Martensitic Ferritic	13 Chrome	SUS410, etc	Rather Bad	55~40	Yes	Yes	Tableware, Cutlery, Gauges Valves, Parts for Pumps
	18 Chrome	SUS430, etc	Fairly Good	65~50	No	Yes	
Austenitic Precipitation Hardening	18-8 Stainless	SUS304, etc	Bad	50~35	No	No	Industrial Parts, Kitchen Appliances
		SUS631, etc	Rather bad				

### ● Reasons For Cutting Difficulty & Influence


Cause	Influence on Tools
Excessive Work-Hardening	Chipping of the flank and increased nose wear.
Low Heat Conductivity	Poor heat dissipation and plastic deformation of edges.
Excessive Deposition with Tools	Deposition of chips causes chipping of cutting edges and tearing of work surface.

### ● Turning Stainless Steels

#### 1) Tool Design (Rake Angle).

#### 2) Recommended insert materials.

#### 3) Recommended Cutting Conditions.



### ● Chip Control (Chip Breaker "UP" Type for Turning Stainless Steels)

#### Features of UP Type Breaker and Configuration

Capable of wide-ranged chip control.

In addition, it shows steady performance due to the strengthened cutting edges.

This is a special breaker developed specially for the machining of stainless steels.

#### Comparison of Wear Resistance

UP Geometry

Conventional Geometry

Workpiece: SUS304  
Tool: PCLNR2525  
CNMG120408 (AC3000)  
Cutting Conditions:  
V = 40~100 (m/min)  
f = 0.35 (mm/rev)  
d = 2.0 (mm)  
T = 10 (min)  
Interrupted Cutting

### ● Milling Stainless Steels

#### 1) Recommended Cutter

#### 2) Recommended insert materials

#### 3) Recommended Cutting Conditions

SEC-ACE Mill UFO Type  
Unique design for superior sharpness and excellent chip removal. It has a Negative-Positive geometry with an approach angle of 45°

Insert	AC325 (Coated)	A30N (Carbide P30)	TiC-Coated	Carbide P30
200 m/min	25	40	55	70
150 m/min	7.5	12	16.5	21
Chip Removal (×10 <sup>3</sup> ) cm <sup>3</sup>	22.5	36	49.5	63

Workpiece: SUS304  
Cutter: UFO4160  
Insert: SFKN12T3AZTN  
Grades: A30N, AC325  
Cutting Conditions:  
V = 150~200 m/min  
f = 0.3 mm/tooth  
d = 3 mm, Dry

### ● End-Milling Stainless Steels

- 1) Recommended Endmills
- 2) Recommended Tool Material
- 3) Recommended Cutting Conditions

SSM-ZX Type - Coated solid spiral endmills  
ZX-Coating - TiAlN compounds coated on the carbide base material, having 3~5 times longer life than normal.  
Conditions - Cutting speed (V) = 30~70 m/min, Feedrate (f) = 0.015~0.05 mm/tooth.

# Exotic Materials Guidance

## ■ Cutting Quench-Hardened Steels

### < Quench-Hardened Steels & CBN >

#### ● Features Of Quench Hardened Steels

Quench-hardened steels with martensite content are excessively hard and strong. Therefore, the cutting resistance, especially thrust force, is high.

#### ● Machining Quench-Hardened Steels (New CBN tools replace; grinding with cutting)

The conventional finishing process for hardened steels has been dependent upon grinding but due to the development of CBN tools which provide better capabilities, more and more users are converting to CBN for finishing of hardened steels

Merits of conversion from grinding to cutting:

- Reducing the cutting time.
- Reducing the cost of equipment.
- Able to perform various operations.


#### ● Sintered CBN (SumiBoron)

Sintered CBN is a new material for cutting tools which is composed mainly of cubic boron nitride and sintered at ultrahigh pressure and temperature

SumiBoron is a sintered CBN tool developed by Sumitomo

Material	Hardness (Hv)	Features	Applications (Workpieces)
BN250	3100 ~ 3300	High Wear Resistance & Fracture Resistance	Hardened Steel: Continuous ~ Light Interrupted Cut
BN300	3300 ~ 3500	High Toughness & Chipping Resistance	Hardened Steel: Medium ~ Heavy Interrupted Cut
BNX20	3200 ~ 3400	High Toughness & Hot Hardness	High Efficiency Cutting
BN600	3900 ~ 4200	Good Thermal Cracking Resistance & Toughness	Hardened Steel & High Speed Cast Iron Turning


### Hardness Of Tool Materials At High Temperature



### < Cutting Quench-Hardened Steels By CBN >

#### ● Cutting of Quench-Hardened Steels and Tool Life

#### Tool Life Diagram In Cutting Carburize-Quenched Steel



Cutting Conditions:  
Depth of Cut, 0.2 mm; feed, 0.12 mm/rev  
Wet; Tool Configuration, -5,-6,5,6,15,15,0,8R

Carbide K10 fails within 2 minutes at 60 m/min, while BN250 has a longer life, some 100 minutes at 100 m/min

#### Comparison Between Surfaces Finished By Grinding & Cutting With BN250

Workpiece: SNCM8 (HRC50) 840 Oil-Quenched, 200 Tempered


	Surface Roughness	Tool	Conditions
Cutting		SumiBoron BN250 SNGN120408	Cutting Speed: 150 m/min Depth of Cut: 0.2 mm Feed: 0.1 mm/rev Dry System
Grinding		WA60K	Peripheral Speed of Wheel: 1450 m/min Peripheral Speed of Work: 30 m/min Depth of Cut: 0.015 mm Use of water soluble grinding fluid

BN250 produces an extremely regular and fine surface finish compared to grinding

#### ● Comparison Between Surfaces Finished By Grinding & Cutting

#### ● Machining Accuracies

#### Dimensional Fluctuation in Boring (The workpiece is rotated by a general purpose lathe)




Workpiece: SCM415 (HRC65), Tool: SumiBoron BN250  
cutting Speed: 100 m/min, Depth of Cut: 0.1 mm, Feed: 0.08 mm/rev, Dry System

The deviation of hole diameter corresponds to a receded amount of the cutting edges due to tool wear and complies with a tolerance width of Class H7 after cutting 200 pcs.

#### ● Milling & Tool Life

#### ● SumiBoron Endmill Example

#### Tool Life In Milling



Workpiece: SKD61 (HRC65)  
Tool: Double-Negative  
Cutting Conditions: Depth of Cut, 0.2 mm; Feed, 0.08 mm/tooth  
Mean Flank Wear: 0.2 mm Reference


#### An Example Of The SumiBoron Endmill :

Workpiece	Applied Tool & Conditions	Results
SKS3 (HRC60)	BNE1025T (25 mm Endmill) N = 1,300 rpm V = 104 m/min b = 0.1 mm d = 7 mm F = 100 mm/min f = 0.08 mm/rev Down-cut	Cutting for 30 min Cutting length: 3 m Minute Wear 

#### ● SumiBoron Jig Boring Tool Example

#### An Actual Example of The SumiBoron Jig Boring Tool

Workpiece: Quenched Parts (Precision Boring)  
Workpiece: SKS3HRC58-50  
Tool: SumiBoron Jig Boring Tool SJB1008 (Dia. 8)



Cutting Conditions:  
V=30m/min  
d=0.1mm  
f=0.05mm/rev  
Dry

Results  
Machining Time : 0.5 min/pcs  
Surface Roughness (Rmax): 1.7 µm  
Bore Concentricity : 1/1000 mm  
Bore Consistency : 5/1000 (30pcs)